

3rd year maintenance				
Sch. XLV-Form No.134				
Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	

Name of work - Maintenance of Road-Tours
 Purnahiga Vijayi Path - Vijai
 Khask ward no - 6 (Ansari tola)
 MMSSY 'cc'
 Block - Ghorasagar.
 Agency : Sunita Den
 Champawat, Koirala, Ghorasagar,
 E. Champaran
 Agreement No - 14 SBD / 2020-21
 Actual Date / comp. :- 15.03.2022

Mainly work has been done

by agency

1. Restoration of Roads

cub with soil - a

2P 8 x 16.20 x 0.80 x 0.30 = 62.20

2P 12 x 10.10 x 0.60 x 0.30 = 43.63

2P 18 x 6.90 x 0.40 x 0.30 = 29.80

2P 12 x 6.80 x 0.70 x 0.30 = 34.27

T 169.90 m³

2. Making up of shore.

done by self, E.P.I.

2P 10 x 18.20 x 1.00 = 364.0

2P 14 x 12.80 x 0.80 = 286.72

2P 18 x 8.60 x 0.70 = 216.72

2P 11 x 5.81 x 0.60 = 76.69

Continuation

T 944.13 m²

Sch. XLV-Form No.134 13

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3. Repair 1 pot hole					
Filled					45
	8	4.80×1.20		=	46.08
	12	3.60×1.60		=	69.12
	3	8.20×0.80		=	19.68
	9	12.10×0.80		=	87.12
				T	222.00 m ²
				unit	218.55 m ²
4. Patch Repair over bottom side					
	8	4.80×1.20		=	46.08
	12	3.60×1.60		=	69.12
	3	8.20×0.80		=	19.68
	9	12.10×0.80		=	87.12
				T	222.00 m ²
				unit	218.55 m ²
5. Cutting & tree by Rail					
ways				unit	4 NO
6. Cut H & shrubs along					
1. way				unit	19.00
7. Trimming of grass & l.					
weeds				unit	
	2	$25 \times 30.00 \times 0.60$		=	900.00
	2	$33 \times 30.00 \times 0.60$		=	1188.00
	2	$1.00 \times 10.50 \times 0.50$			10.50
				T	2098.50 m ²

Continuation

Sch. XLV-Form No.134 14

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
8. Main 15 ft R - 15.00					
by way			A.L. 0.93 km		
9. Main 15 ft 2009 & K.M.					
Shan -			A.L. 1.87 km		
10. Main 15 ft by					
then double -			186 NO		
11. Main 21 ft 1.00 by					
4 lot chab 1 ft 1.00 by					
2 x 62 x 30.00 x 0.10				2	372.00
2 x 1 x 150 x 0.10				2	1.0
					+ 373.00 02

Abstract & cost.

1. Restoration of lawn			
cuts with soil			
P.			
169.90 m ² @ 386.14			9,656.05:
2. Makay up of shadow			
111			,
Q			
944.13 m ² @ 57.56			54,344:
3. Repair of lot hub by			
field			

Sch. XLV-Form No.134

15

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
218.55 m^2 (2) 9. 423=61	9	92582			
4. Patch of grass over bitumens surface					
	P.				
218.55 m^2 (2) 9. 304=75	1	66605			
5/11 (1) Cylindrical bank & trees by the way					
	P.				
4 NO (2) 9. 109.74	9	439			
4/11 (1) Cylindrical shrubs by the way					
	P.				
19 NO (2) 9. 672	2	128			
7/11 (11) Tree stumps & woods					
	P.				
209.850 m^2 (2) 9. 2.24	9	4701			
8/11 (2) 70-15 P. trees & 1/2 side					
	P.				
186 NO (2) 9. 509.41	9	94758			
9/11 (2) Patches of thick grass by the way					
	P.				
373.09 m^2 (2) 735=44	1	274319			
14 9. 70-15 P. grass					
	by way				
	Continuation				

Sch. XLV-Form No.134 16