

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of locality: Bugar Bheraul					
road to Badli village					
Chowdhary Talwar					
Name of Agency - Alimnash Kumar					
Jaiswal At-Nahar PP					
Road - Bugar					
Agreement: 47 S.B.D/2020-21					
Date of start: 21.01.2021					
Date of completion 20.01.2022					
Date of actual completion 07.07.2021					
(1) Resignation rainwater Berm					
with soil measure					
2 x 2 x 30 x 1.125 x 0.30 =					40.5 m ³
2 x 4 x 25 x 1.10 x 0.25 =					55 m ³
2 x 5 x 8.5 x 1 x 0.20 =					17 m ³
					Total 112.5 m ³
(2) making up of Berm should					
2 x 6 x 20 x 0.60 =					144 m ²
2 x 5 x 20 x 0.75 =					150 m ²
2 x 8 x 25 x 0.80 =					320 m ²
2 x 6 x 16 x 0.91 =					174.72 m ²
					Total = 788.72 m ²
(3) Repair of Potholes filled					
with 75mm WBM					
8 x 2.5 x 1.15 x 0.075 =					1.725 m ³
6 x 2.8 x 2.1 x 0.075 =					2.64 m ³
8 x 3 x 2.5 x 0.075 =					4.5 m ³
3 x 2 x 2 x 0.075 =					0.9 m ³
Continuation					Total: 9.77 m ³

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
BF				Rs 163620 ⁰⁰
(i) White washing of parapet walls of ch works & free drains				
Qty = 42 m ² vide TMB P-60				
@ 16.34/m ²				Rs 686 ⁰⁰
				Rs = 164306 ⁰⁰
Add GST 12%				Rs = 19717 ⁰⁰
Add L. cess 1%				Rs = 1643 ⁰⁰
				Rs = 185666 ⁰⁰
less 17.87% Below (-)				Rs = 33178 ⁰⁰
				Rs = 152488 ⁰⁰

11-01-20
re

A

06/08/2025

[illegible]

[illegible]

ABSTRACT of COST

- (1) Restoration joints

Room with Soil room

$$Q_{f,2} = 99.29 \text{ m}^3$$

vide TBM page - 52

@ 351.04/m³

$$R_3 = \underline{34851.00}$$

- (2) making up of Berm shoulder

Qfy: G90-8m2 vide TMB
page 52

$$Q8 = \underline{39065.00}$$

- (3) repair of potholes filled