

5th year Maintenance

73

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: → Hillsa Noorbanari Kapsiyawan road to Trilok Bigha.					
Agency: → Chashi Prakash.					
Ass. No. - 79/SBD/2017-19					
Date of Completion - 28.05.2020					
① Restoration of. Patch cut etc.					
2x6 x 30.0 x 0.47 x 0.20 = 50.76 m ³					
100% = 50.76 m ³					
② Making up of Berms/ Shoulder. — d. —					
2 x 9 x 30.0 x 0.50 = 270 m ²					
③ Repair of potholes. Filled with 75 mm. ---					
6 x 4.55 x 2.35 x 0.075 = 4.811					
= 4.81 m ³					
④ patch repair over. poth holes. —					
6 x 4.55 x 2.35 = 64.155 m ²					
= 64.155 m ²					
⑤ Patch repair over. bituminous. Surface.					
Qty. Same Item - ④					
= 64.155 m ²					

Continuation

Continuation