

2nd year maintenance Bill

18

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
N/W :-	REO	Path	Shivshankarpu		
		Samastipur	to Salaman		
		Khan	Haya madarsa		
		Tak	under mm Gsy (SC)		
Agency-	Smt. Juli Kumari				
	Nathagar				
Agg No-	38/SBQ/2021-22				
A/D/O/c-	02.06.2021				
Period-	03.06.22 To				
	02.06.2023				
Rate. 0.37/- below rd Per Agg.					
Measurement Record					

① Restoration of rain cuts.					
3 x 3.20 x	$\frac{1.00 + 0.90}{2}$		x 0.300		7.30 m ²
7 x 1.50 x	$\frac{1.15 + 1.00}{2}$		x 0.300		3.39 m ²
5 x 2.30 x	$\frac{1.20 + 0.90}{2}$		x 0.30		3.62 "
6 x 3.00 x	$\frac{1.15 + 0.90}{2}$		x 0.300		5.54 "
7 x 2.00 x	$\frac{1.15 + 1.00}{2}$		x 0.300		4.52 "
					24.35 m ²

② making up of drains/					
Shoulders					
3 x 3.00 x 1.20					28.80 m ²
4 x 4.50 x 0.80					14.40 "
6 x 4.20 x 1.00					25.20 "
3 x 4.10 x 0.75					11.69 "
6 x 3.20 x 1.10					21.12 "

(Continuation)



Sch. XLV- Form No. 134

[illegible]

materials Consumption

Earth-	44.53%
--------	--------

ships -	0.375 m ²
---------	----------------------

Bitumen -	0.0309 mT.
-----------	------------

Emulsion RS-2 0.0309 mT

5706124
CONE

(Continuation)