

certify That This M. B. counting
100 (one hundred) Machine Number
Ratendra Prasad

31

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
4th year Maintenance					
Work - Cont. of Road from					
Abjyang Kumaita					
Path ke 2 km me					
Bajaj sharma Ghar					
to upswath kenduatar.					
Any Gramin lenx.					
Path unde mmhsy (sc)					
Agency - Gaurar Sagar					
Shambhugang, Banka					
Agg. No- 28 SBD / 2018-19					
Date of start - 10.08.2018					

Period - 14.05.2018 - 13.06.2018

1) Restoration of Raincut /

Berms - E5.

$$3 \times 7.00 \times 1.10 \times 0.30 = 6.93 \text{ m}^3$$

$$5 \times 6.00 \times 1.00 \times 0.30 = 9.00 \text{ m}^3$$

$$3 \times 7.50 \times 1.25 \times 0.30 = 8.44 \text{ m}^3$$

$$5 \times 5.00 \times 0.90 \times 0.30 = 6.75 \text{ m}^3$$

$$4 \times 6.00 \times 1.15 \times 0.30 = 8.28 \text{ m}^3$$

$$1 \times 3.85 \times 0.95 \times 0.30 = 1.10 \text{ m}^3$$

$$T = 40.49 \text{ m}^3$$

2) making up of

Berms shoulder shif

Excess Soil from

the shoulder surface - E5

(Continuation)

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area	
	No.	L.	B.	D.		
ABSTRACT OF COST						
(1) Restoration of Rain water						
Berms with Sac. ES						
Qty. vide TMB P. No. (31)					40.49 m ²	
@ Rs. 352.26/m ²					Rs. 14,264=00	
(2/2) making of Berms shade						
Shitty excess soil-						
Qty. vide TMB P. No. (32)					222.17 m ²	
@ Rs. 51.72/m ²					Rs. 11,490=00	
(3/a) maintenance of						
Qty. vide TMB P. No. (32)					0.08 km	
@ Rs. 1067.44/km					Rs. 85=00	
(4/10) maintenance of 200m						
7 km Stm - ES						
Qty. vide TMB P. No. (32)					0.09 km	
@ Rs. 576.34/km					Rs. 52=00	
					Rs. 25,891=00	
Less as/As 0:10 below					Rs. 26=00	
					Rs. 25,865=00	
madhukhi 16/06/24 no						
16/6/24 MR						

(Continuation)