

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
Name of Road →					makaspur mukha
					mantri To Karampur Road
					Under mmsy (SC)
Name of Agency →					Sri vivash chandra
					Chaudhary
Agreement No →					43/SBD/2018-2019
					Actual Date of Completed
					3-07-2020
Date of measurement →					4-07-2020
(1/15.1)					Restoration of Raincure
					Berms with soil medium
	40		40		El/L

$$2 \times 5.00 \times \frac{1.10 + 1.00}{2} \times 0.300 = 3.15 \text{ m}^3$$

$$2 \times 6.50 \times \frac{1.50 + 1.20}{2} \times 0.300 = 5.265 \text{ m}^3$$

$$2 \times 7.10 \times \frac{1.60 + 1.30}{2} \times 0.300 = 6.177 \text{ m}^3$$

$$4 \times 6.30 \times \frac{1.50 + 1.20}{2} \times 0.300 = 10.206 \text{ m}^3$$

$$6 \times 5.50 \times \frac{1.20 + 1.10}{2} \times 0.300 = 11.385 \text{ m}^3$$

$$2 \times 5.00 \times \frac{1.30 + 1.10}{2} \times 0.300 = 3.6 \text{ m}^3$$

$$= 39.723 \text{ m}^3$$

(2/15.2)

making up of Berms

Shoulder, Stripping

excess soil from the

Shoulder do — do — El/L

$$5 \times 3.20 \times 1.12 = 16.8 \text{ m}^2$$

$$6 \times 7.40 \times 1.00 = 44.4 \text{ m}^2$$

(Continuation)

