

3rd year maintenance

58

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Maint. of road from					
Sekhona TO Lohi.					
Agency:- MPSRILKA Construction.					
Agg. No:- 46800/2021-22.					
Actual completion date:- 01/06/2022.					
<u>Record Entry</u>					
1.	Restoration of				
	draincuts do—				
	8 X	6.89	X 1.18	X 0.30 =	19.51 m ³
	11 X	6.24	X 1.16 X	0.30 =	23.89 m ³
	7 X	5.07	X 1.12 X	0.30 =	11.92 m ³
					<u>55.32 m³</u>
2.	making up of earthen				
	shoulders do—				
	2 X	7 X	5.72 X	1.28 =	102.50 m ²
	2 X	9 X	6.22 X	1.34 =	150.03 m ²
	2 X	12 X	5.44 X	1.30 =	169.73 m ²
					<u>422.26 m²</u>
3.	Repair of potholes				
	with 75 mm WBM do—				
	7 X	3.48	X 1.22 =		29.72 m ²
	5 X	2.06	X 1.07 =		11.02 m ²
	5 X	3.38	X 0.91 =		15.38 m ²
					<u>56.12 m²</u>
4.	patch repair over				
	potholes do—				
	Qty. same as above: 56.12 m ²				

Continuation

Continuation