

4th Year Maintenance

61

Sch. XLV-Form No. 134

Mr. Leo Ram Nasran audit here
 Details of actual measurement
 Particulars
 No. L. B. D. Contents of area

(1) Restoration of drain cut
 with Soil - T/S

6	8.0	0.90	0.60	25.92
5	4.0	0.80	0.50	8.00
4	9.0	0.70	0.40	10.08
12	5	0.80	0.3	14.4
7	3	0.6	0.5	6.3
5	13	0.565	0.6	22.03
				86.73

(2) Maintenance of Earthwork
 Shoulder

2x	5x30x0.65	=	195
2x	3x30x0.300	=	54
2x	7x30x0.500	=	210
2x	20x0.550	=	22
2x	10x0.700	=	14
			495m ²

(3) Repair to pot holes Mix
 Seal Surfacing

2	1.9	1.2	=	4.56m ²
3	1.5	1.1	=	4.95m ²
5	2.1	0.95	=	9.975m ²
4	3.1	0.65	=	8.06m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Total					110284
less 10% below					11028
					99256
<u>Material Statement</u>					
Soil					86.73 m ³
Bitumen					0.39 MT
Stone cur - S.S					m ³