कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, त्रिवेणीगंज।

पत्रांक 2227 /त्रिवेणीगंज, दिनांक 25/11/25

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, त्रिवेणीगंज।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव, बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय:- मुख्यमंत्री ग्राम सम्पर्क योजना (MMGSY SC) अंतर्गत आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि मुख्यमंत्री ग्राम सम्पर्क योजना (MMGSY SC) अंतर्गत इस पत्र के साथ संलग्न पथ से संबंधित अधियाचना विहित प्रपत्र में तैयार कर समर्पित है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0 :—यथोक्त।

विश्वासभाजन

भीष कार्य विभाग प्रमण्डल विकास

Rural Works Department

	THE STATE OF	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is			1	Cormat
MMGSV		A 11 - 4-1	aant R	eauisitic)II I	ruimat
MMCCV	ISCI	Allou	Terre ve	.Oq		and the second s

1			10	IMIGST	(30) 11113		I					
N	Name of Division :- Triveniganj					Agreement Amount		411 - 1	Total	Value of		Remarks/ Actual
S.			Name of	Administrative Amount		(in Lacs)		Allotment Received	Expenditure (in Lacs)	Measurment (in Lacs)		Dt. Of Completion.
Ne	Year	Name of Road	Contractor	Length	Amount	Main Work	Maintenance	(in Lacs)	(111 124.00)	(22.00)		
L				(in Km.)	(in Lacs)	7	8	9	10	11	12	14
1	2	3	4	5	6			MO				
	2018-19	World Bank Sadak Ward No- 09 to Koriyapatti Gram Tak.	M/S Omee Aryan Construction	1.130	77.30000	62.34114	6.18500	24.11262	24.11262	57.03514	32.92252	Completed
+	Total				77.30000	62.34114	6.18500	24.11262	24.11262	57.03514	32.92252	

Executive Engineer

D.) Triveniga

FORM GFR - 19 - A

(See Government of India's Decision (i) below Rule - 150) Form of Utilization Certificate up to 21.11.2025

1			(MMGSY-SC- Programming Fund) Balance Amount								
S	i. No.	Name of Scheme	Sanction No. & Date with Amount (In Lacs)	Total Amount Received (In Lacs)	Particulars	(in Lakh) Bank+ CFMS					
		Construction	Total Allotment Opening Balance	11862.38021	Certified that out of Rs. 11862.38021 lakh deposited in BRRDA S.B.I., Bailey Road Patna a sum of Rs. 11711.39853 lakh has been utilized for the purpose of schemes for which it was sanctioned, Balance- 150.98168 Lakh	150.98168					
			Total Allotment Opening Balance as on 31.03.2024 By CFMS Rs	10892.11570	•						
	1		Letter No-09 encl, dated-24.04.2024 by CFMS	31.43062	and the second of the second o						
			Letter No-23 encl, dated-16.05.2024 by CFMS	81,95805							
1	1		Letter No-35 encl, dated-13.06.2024 by CFMS	40.78835							
	1		Letter No-50 encl, dated-12.07.2024 by CFMS	111.38056							
١.			Letter No-32 encl, dated-18.06.2025 by CFMS	30.22569	. 7 .2 0 0 1						
1	l _u	nder MMGSV	Letter No-15 encl, dated-18.06.2025 by CFMS Letter No-15 encl, dated-10.05.2025 by CFMS	8.27501							
		(SC) Schome	Letter No-161 encl, dated-20.03.2025 by CFMS	33.99653	Total CFMS Allotment Rs :- 11505.88769 Lakh						
	1	` '	Letter No-148 encl, dated-28.02.2025 by CFMS	4.13381	CFMS Expenditure Rs11482.95240 Lakh	22.93529					
			Letter No-127 encl, dated-13.01.2025 by CFMS	53.25284	Balance Rs 22.93529 Lakh						
	1		Letter No-116 encl, dated-06.12.2024 by CFMS	2.85391							
			Letter No-107 encl, dated-21.11.2024 by CFMS	7.12659	· · · · · ·						
			Letter No-101 encl, dated-05.11.2024 by CFMS	17.92354							
			Letter No-86 encl, dated-07.10.2024 by CFMS	21.18173							
			Letter No-73 encl, dated-03.09.2024 by CFMS	70.70270							
		1 4 2 3 4 4									
	1										
	L		Total CFMS	11505.88769	가는 가 성관(전) 가는 것으로 가 되었다.						
	Cer	rtified that I have sa	atisfied myself that the condition on which the grants in aid sanctioned have	neen duly fulfilled / are being fulfill	ed and that I have Evercised the following Checks to see that the monor was a trail to the						

nctioned have been duly fulfilled / are being fulfilled and that I have Exercised the following Checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Works have been supervised by Executive Engineer / Superintending Engineer.

Periodical inspection has been conducted by A.E. / Executive Engineer / Superintending Engineer.

2 iii Construction materials have been tested.

Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer. iv

All other Codal formalities have been observed.