

1

1

1

1

1

1

1

1

4th year maintenance

75

Sch. XLV-Form No. 134

[illegible]

①	Restoration of haircuts of Beny	
	$15 \times 5.25 \times 1.25 \times 0.30 = 29.531 \text{ m}^3$	
	$20 \times 4.95 \times 1.25 \times 0.30 = 37.125 \text{ m}^3$	
	$2 \times 15 \times 3.95 \times 1.25 \times 0.30 = 44.4375 \text{ m}^3$	
	$2 \times 16 \times 5.25 \times 1.30 \times 0.30 = 65.52 \text{ m}^3$	
	$20 \times 4.00 \times 1.25 \times 0.25 = 25 \text{ m}^3$	
		$= 201.613 \text{ m}^3$
②	making up of Beny	
	$15 \times 9.35 \times 1.30 = 184.875 \text{ m}^3$	
	$2 \times 20 \times 9.95 \times 1.25 = 247.50 \text{ m}^3$	
	$2 \times 15 \times 9.50 \times 1.25 = 93.75 \text{ m}^3$	
	$2 \times 16 \times 9.65 \times 1.35 = 144.48 \text{ m}^3$	
		$= 431.555 \text{ m}^3$

Continuation

Qand - 4050m

ABSTRACT of work

77

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of rain water —					
Plinth P No (25)					
201.613m ² @ 378.26/m ²					762622
② making up of Ben Plinth P No (25)					
405m ² @ 58.12/m ²					235592
③ Repairs of Potholes filled with Bitumen					
Plinth P No (28)					
84.355m ² @ 363.86/m ²					306932
④ Patch repair of over Pot holes —					
Plinth P No (28)					
84.355m ² @ 310.80/m ²					262172
⑤ Patch repairs over BT surface —					
Plinth P No (28)					
84.355m ² @ 330.45/m ²					278752
⑥ maintenance of HP culvert —					
Plinth P No (28)					
022m ² @ 109.87/m ²					22192
⑦ maintenance of Road sign —					
Plinth P No (28)					

Continuation

C-4 1868252

Bf 186828

॥