


4th Year Maintenance

Sch. XLV-Form No.134

31

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Rampurwa Harijan Tola to Kopeiri Tola Dem Tola (MMSY)					
Agency- Ajay Kumar Dubey					
Agreement No- 59 SBD/2020-21					
Date of start - 17/03/2020					
Actual date of completion - 15/12/2021					
4 th Year Maintenance? 16/12/2024					
Period } to 15/12/2025					
① Restoration of Rain cuts					
1 X	7.10	X	1.10	X	0.25 = 1.95m ³
1 X	6.15	X	0.90	X	0.30 = 1.66m ³
2 X	9.40	X	1.25	X	0.25 = 5.62m ³
1 X	7.50	X	1.10	X	0.30 = 2.47m ³
1 X	8.15	X	1.15	X	0.25 = 2.34m ³
2 X	10.40	X	1.20	X	0.30 = 7.20m ³
1 X	11.40	X	1.25	X	0.25 = 3.44m ³
2 X	6.85	X	1.20	X	0.25 = 4.11m ³
					28.79m ³
② Maintenance of earthen shoulder					
3	X	6.40	X	1.10	= 19.80m ²
2	X	7.10	X	1.20	= 17.04m ²
3	X	9.50	X	1.15	= 32.77m ²
2	X	7.50	X	1.10	= 16.50m ²
1	X	6.50	X	1.20	= 7.80m ²
2	X	10.40	X	1.25	= 26.25m ²
1	X	8.10	X	1.20	= 9.72m ²
Continuation					129.88m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Q. VTNB/32(5) = 56.16 ^h					
e. R. 256.21 ^h					14389=0
271.24/1 ^h					15233=0
(4) Maintenance of stable culvert					
Q-VTNB/33(5) = 2 Nos					
e. R. 2273 = 47/each R.					4547=0
(5) Maintenance of Trees by the road side					
Q-VTNB/33(6) = 60 Nos					
e. R. 498 = 96/each R.					29938=0
(6) Maintenance of road sign					
Q-VTNB/33(7) = 0.12 km					
e. R. 1054.28/km R.					126=0
(7) Maintenance of zoom stone					
Q-VTNB/33(8) = 0.14 km					
e. R. 688 = 17/km R.					96=0
(8) Repair to potholes 20mm					
per					
Q-VTNB/32(5) = 56.16 ^h					
e. R. 271.24/1 ^h					15233=0
					R. 113914=0
Add 1% L. cess (+)					1139=0
Add 12% GST (+)					13670=0
					R. 128723=0
Less 0.01% below (-)					13=0
					R. 128710=0
 02/12/25 AE					
A.P. Singh					
20/11/25					
J.E					

Continuation