

2nd year maintenance.

62

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work - main of Road from					
PMGSY Road to Naya					
to 19 Mahmadgar.					
N/Agency - Ramesh Kumar Singh,					
Agg. No - 290 SBD/2020-21					
D.O.S! - 08.09.2020					
A.D.O.C! - 27.03.2022					
Date of measurement.					
(1/1) Restoration of rain					
cuts do do - E/S					
	7x	8.00x	0.80x	0.30 =	13.44m ³
	8x	7.00x	0.70x	0.30 =	11.76m ³
	7x	6.00x	0.90x	0.30 =	11.34m ³
	5x	9.00x	0.80x	0.30 =	10.80m ³
				Qty =	47.34m ³
(2/2) main of earthen					
shoulder do do - E/S					
	9x	7.00x	0.80	=	50.40m ²
	7x	9.00x	0.70	=	44.10m ²
	5x	8.00x	0.60	=	24.00m ²
	7x	9.00x	0.80	=	50.40m ²
	9x	8.00x	0.70	=	50.40m ²
	7x	7.00x	0.80	=	39.20m ²
				Qty =	258.50m ²



Scanned with OKEN Scanner