

N/W-L100-Kachha Rupo Road to Kewla (Track 76)

Shedule XLV Form No. 134.

Narada

DIVISION

Paksubarman

SUB-DIVISION

Measurement Book

2611

Vinay Const.

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
2014 on R/A C bill				
Quantity for new H.P. ducts (1000 mm Dia)				
1 Elm in excavation in foundation trenches do do				
H.W. - 2x 6.40x1.40x1.50=27.090 m ³				
Below pipe 1x 4.80x1.50x0.365=2.708 m ³				29.798 m ³
2 Providing 1508 P.C. layelling course in foundation do do				
H.W. - 2x 6.45x1.40x0.150=2.709 m ³				
3 P.V. plain cement concrete No. in 8.15 excavation do do				
4 Providing 115 P.C. layelling course in foundation do do				
Below pipe 1x 4.31x1.50x0.250=1.885 m ³				
5 Providing 2 lying P.C. pipe No.3 for culvert for road class bedding do do				
3x 2.50=7.50 m				
6 P.V. plain cement concrete No. in substructure do do				
H.W. - 2x 6.15x (0.30+0.40)x1.80=14.59 m ³				
Footpath 2x 6.15x 0.40x0.60=2.952 m ³				
Less for pipe 2x 0.785x0.250x0.522=0.1979 m ³				15.863 m

Rs 11125

Ae

J.E


Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
11. Qty taken Vid. M/S page				BF 85353064=01
20. 18 (taken mt- 28.02.25) — 4.9661 m ³				
② 18.735493/m ³ — 15.30,830=				
12. Providing RCC Blgs in duct slab				
— do — do —				
Qty. taken Vid. M/S page				
78. 18 — 3.6864 m ³				
② 18.7448.06/m ³ — 18.27,580=				
13. Providing Wesp. Ho. in plain cement concrete — do — do —				
Qty. taken Vid. M/S page mt- 18.11.25				
				18.5925496=00
Add L.C @ 1% — — —				+ 18.59255=3
Add Seigniorage fee — — —				+ 18.98600=00
				18.6083357=00
Add GST @ 18% — — —				348.1095,005=0
				18.49833484=00
				11.18,854=00
Less:- 17.21% 08 pps agreement — 18.19,35,385=00				18.5942959=00
14. Defect amount of 18.01.2018				
bell Vid. M/S page mt. 11 — 18.35,529,688=00				18.24,132,71=00
15. 12/12/25				
15/12/25				
16/12/25				


अधियाचना हेतु प्रमाण-पत्र

प्रमाणित किया जाता है कि RRSMP (SC) योजनान्तर्गत :-


1. पथ / पुल L100-KACHNA RUPO ROAD TO KEWLA (TRACK76) में कराये गये कार्य की गुणवत्ता जांच की गयी है जो निर्धारित मानक / विशिष्टियों के अनुरूप है।
2. अद्यतन कराये गये कार्य की मापी संबंधित मापी पुस्तिका में दर्ज है जिसका सत्यापन कर लिया गया है।


18/12/25

कनीय अभियंता
ग्रामीण कार्य विभाग


18/12/25

सहायक अभियंता
ग्रामीण कार्य विभाग


18/12/25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल नवादा।