

# 3rd year maintenance

25

Sch. XLV—Form No. 134

| Sch. XLV—Form No. 134            |                               |    |    |    |                  |
|----------------------------------|-------------------------------|----|----|----|------------------|
| Particulars                      | Details of actual measurement |    |    |    | Contents of area |
|                                  | No.                           | L. | B. | D. |                  |
| Name of work- Maint of Road from |                               |    |    |    |                  |
| Nuvodag Pmgar Road to Kladipra   |                               |    |    |    |                  |
| Samudika Phavan via Molong       |                               |    |    |    |                  |
| Aethu- Yeganta Menta k. Ghe      |                               |    |    |    |                  |
| Agency - Subham Ceru             |                               |    |    |    |                  |
| Agreement No 172-830/2019-20     |                               |    |    |    |                  |
| Det of stak - 03.07.19           |                               |    |    |    |                  |
| Date of actual comp - 02.12.20   |                               |    |    |    |                  |

## Work Done

- (1) Restoration of Rainfall
- do all comp job

|       |                     |                |                       |
|-------|---------------------|----------------|-----------------------|
| 12x15 | $\frac{1.1+0.8}{2}$ | $\times 0.3 =$ | 51.30 m <sup>3</sup>  |
| 9x18  | $\frac{0.7+0.5}{2}$ | $\times 0.3 =$ | 29.6 m <sup>3</sup>   |
| 14x16 | $\frac{1+0.7}{2}$   | $\times 0.7 =$ | 57.12 m <sup>3</sup>  |
| 3x12  | $\frac{1.1+0.8}{2}$ | $\times 0.3 =$ | 16.26 m <sup>3</sup>  |
| 6x19  | $\frac{0.8+0.5}{2}$ | $\times 0.3 =$ | 22.23 m <sup>3</sup>  |
| 7x18  | $\frac{0.9+0.6}{2}$ | $\times 0.3 =$ | 28.35 m <sup>3</sup>  |
| 5x14  | $\frac{1.1+0.8}{2}$ | $\times 0.3 =$ | 19.95 m <sup>3</sup>  |
|       |                     |                | 218.37 m <sup>3</sup> |

- (2) Maint of earthen Shant

|                 |                     |     |                      |
|-----------------|---------------------|-----|----------------------|
| do all comp job |                     |     |                      |
| 8x18            | $\frac{1.1+0.8}{2}$ | $=$ | 136.8 m <sup>3</sup> |
| 6x25            | $\frac{1+0.8}{2}$   | $=$ | 135.0 m <sup>3</sup> |
| 11x23           | $\frac{0.3+0.7}{2}$ | $=$ | 202.4 m <sup>3</sup> |
| 4x21            | $\frac{1.1+0.9}{2}$ | $=$ | 84.0 m <sup>3</sup>  |

Continuation



Scanned with OKEN Scanner