

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maint. Bldg					
N/W - Const. of Road from					
SH to Pampur Siman					
to Khor Pakar Bazar					
work.					
Agency:- M/S Deyendra Kumar and					
Company.					
Ag. No - 276 SBD/2020-21					
Date of work order - 02.12.20					
Actual date of completion:- 26.06.21					

1.	Restoration of main				
	cut and berm.				
	$6 \times 5.8 \times .8 \times .30 = 8.35 m^3$				
	$7 \times 4.3 \times .90 \times .25 = 6.77 m^3$				
					15.12 m ³
2.	making up berm				
	and shoulder.				
	$8 \times 6.25 \times .85 = 42.50 m^2$				
	$6 \times 5.75 \times .80 = 27.60 m^2$				
					70.10 m ²
3.	Maint. of H.P				
	Culvert do.				
	do - E19				1 No.

Continuation P. T. O

Scanned with OKEN Scanner