

Schedule XLV-FORM No. 134

86

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
S/W:- Birendra Sahi ke Dukan to Brahmandan Tadar ke Ghar Tak.					
Agency:- Adarsh Construction					
Ag No:- 188 SRD/2019-20					
D.O:- 14.09.2019					
Actual Date of Completion:- 27.10.2020					
Measurement					

① Restoration of Rain Cuts with
soil - do tech sp.

$$3 \times 8 \times 1.20 \times 0.30 = 8.640$$

$$5 \times 7 \times 1.120 \times 0.3 = 11.76$$

$$6 \times 8 \times 1.10 \times 0.3 = 10.56$$

$$5 \times 5 \times 1.25 \times 0.3 = 9.375$$

$$4 \times 6 \times 1.50 \times 0.3 = 10.80$$

$$8 \times 7 \times 1.125 \times 0.3 = 18.90$$

$$= 70.03543$$

② Making up loss of material
irregularities - do - tech sp

$$10 \times 8.0 \times 1.25 = 100.00$$

$$8 \times 5.0 \times 1.120 = 44.80$$

$$5 \times 7.0 \times 1.125 = 39.375$$

$$9 \times 6.0 \times 1.120 = 60.48$$

$$8 \times 8.0 \times 1.125 = 72.00$$

$$6 \times 10.0 \times 1.30 = 78.00$$

$$3 \times 12.0 \times 1.25 = 45.00$$

$$= 419.655 \text{ m}^2$$

③ Repair of pot holes mss
road - do - tech sp

$$15 \times 0.90 \times 0.90 = 12.150$$

$$12 \times 0.6 \times 0.6 = 4.320$$

$$18 \times 0.9 \times 1.20 = 19.44$$

$$6 \times 1.2 \times 0.9 = 6.48$$

$$5 \times 2.50 \times 2.0 = 25.00$$

$$8 \times 2.0 \times 1.50 = 24.00$$

$$= 91.39 \text{ m}^2$$

Continuation

