

Bad on a/c running Rail
No measurement.

only abstract.

8

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
9th site cleaning & grubbing. TMB, page (6) Qty = 0.23 M ³ .					
Qty. 73248.25/M ³ =				1	16847.20
(10) Contn of Subgrade. TMB, page (6) Qty = 512.50 M ³					
Qty. 251.42/M ³ =				1	130110.20
(13) Box cutting. TMB, page (6)					
Qty = 150.94/M ³ @ 1.181.19/M ³ =				1	27349.20
(14) Contn of LTB WRT. TMB, page (6)					
Qty = 129.28 M ³ @ 2991.84/M ³ =				1	387084.20
(15) PIV & laying in B.H.II					
TMB, page (6) Qty = 90.87 M ³					
Qty. 5492.48/M ³ =				1	499102.20
(16) PIV & laying P.C.M.S.S.					
TMB, page (6) Qty = 539.07 M ³					
Qty. 8071.15/M ³ =				1	4350896.20
(17) PIV & fixing typical type of M.M.L.S. & inform sign board.					
TMB, page (6) Qty = 0.2 M ³					
Qty. 12625.29/each =				1	25246.20
Total p. 5436634.20					
Add 18% LST				1.18	978594.20
Add 1% (about LSS)				1.01	54366.20
Add 8%				1.08	26000.20
Total p. 6495594.20					
0.02% LSS				1.02	1299.20
Total p. 6494295.20					
less previous payment.				1.1	3085969.20
Total p. 3408326.20					
Annex 22/11/21 S.E.					
Material Statement					
Nil					

Continuation

Annex
22/11/21
S.E.