

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year maintenance					
will					
N/wall - Maintenance of road from L. Chavara					
Mathya S. Lashery					
Per under survey.					
N/Agency - in wintering					
Common -					
D/Side					
D/Complete					
Actual date of complete - 07/07/2023					
Date of survey - 05/07/2024					
1.) Restriction of materials					
beam - do - do -					
are complete					
5 x 7.50m x 1.10m x 0.20 = 12.375m ³					
3 x 2.50m x 1.10 x 0.20 = 0.25m ³					
2 x 9.20m x 1.10m x 0.20 = 6.02m ³					
87 = 20.695m ³					
2.) Maintenance of earth					
Shoulder - do - do -					
are complete					
4 x 13.50m x 1.10m = 59.40m ²					
2 x 6.30m x 1.10m = 13.86m ²					
1 x 5.50m x 1.10m = 6.05m ²					
1 x 4.10m x 0.90m = 3.69m ²					
Continuation 84 = 83.0m ²					


Continuation

$$q_h \sim 83.0 \text{ m}^2$$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B1A	4	16552 m
6/15/22	Cutting up branches of tree - do do - all complete				
94 - 0.5	N15W1H - side - MB P - (30)				
	@ P - 10632/m ² - P - 533 m				
7/15/22	Cutting up shrubs from road way - do - do - all complete				
94 - 11.0	N15W1H side - MB P -				
	@ P - 6.58/m ² - P - 72 m				
8/15/22	Trimming up grass - do - do - all complete				
94 - 135	H ² side - MB P -				
	@ P - 2.18/m ² - P - 294 m				
9/15/22	white washing on - do - do - all complete				
94 - 16	m ² side - MB P -				
	@ P - 10.81/m ² - P - 221 m				
	P - 17672 m				
	Less 10 ft. Letw - P ₅				
	Agreed - P - 17672				
	P - 15905 m				

Continuation



 J. K. 9774

①	Restoration of Reinment			
	do-do all complete			
	5 x 7.5m x 1.10m x 0.30			12.375m ³
	3 x 2.5m x 1.10m x 0.30			2.25m ³
	2 x 9.25 x 1.10 x 0.30m			6.0243
	3 x 1.0m x 1.5m x 0.30m			0.90m ³
			Total =	21.60m ³
②	Maint. of Earthen			
2	shoulder do-do			
	all complete.			
	4 x 13.50m x 1.10m			59.40m ²
	4 x 13.25m x 1.10m			58.30m ²
	2 x 4m x 1.0m			8.00m ²
			Total =	125.70m ²

Continuation

Continuation