

NMGSY(Sc) LO28 to Ghoryara - 2.243 km
Ag.No- 11 SBD/21-22

Shedule XLV Form No: 134.

Serglati

DIVISION

Serglati

SUB-DIVISION

Aharanjay Kumar Singh

Measurement Book

1358

3rd year maintenance bill

61

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W maintenance of road from 1028 to 1035 house					
Agency 1 - Dhananjay Kumar Singh					
Agreement No - 11/SRD/2021-2022					
Date of start 1 - 9/7/2021					
Date of completion :- 8/7/2022					
①	Restoration of Raincuth				
	Berms do do				
	$3 \times 30 \times 1.00 \times 0.30 = 27.00m^3$				
	$2 \times 25m \times 0.90 \times 0.30 = 13.50m^3$				
	$3 \times 28 \times 0.90 \times 0.30 = 22.68m^3$				
	$2 \times 25 \times 0.80 \times 0.30 = 12.00m^3$				
	$2 \times 20 \times 0.80 \times 0.30 = 9.60m^3$				
	$2 \times 10 \times 0.80 \times 0.30 = 4.80m^3$				
	<u>89.58</u>				
	Say Limit = 89.74m ³				
②	making up of Berms/				
	Shoulder do do				
	$2 \times 6 \times 30 \times 1.00 = 360m^2$				
	$2 \times 2 \times 28 \times 1.00 = 112.00m^2$				
	<u>472.0</u>				
Continuation					

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT of COST</u>					
<u>Item-1</u>	Restoration of Reinconly Berm do de @um-vide TMB P.No-61 item no - 1				
	28.74 m ³ @ 396.73 / m ³ Rs = 35206 = 00				
<u>Item-2</u>	making up of Berm/ shoulder do de @um-vide TMB P.No-61 item no - 2				
	472.0 m ² @ 59.66 / m ² Rs = 28160 = 00				
<u>Item-3</u>	Repair of Potholes filled with 75mm --- @um-vide TMB P.No-61 item no - 3				
	0.66 m ² @ 9392.24 / m ² Rs = 2442 = 00				
<u>Item 4</u>	Patch repair over potholes with 20mm --- @um-vide TMB P.No-62 item no - 4				
	86.9 m ² @ 2401.37 / m ² Rs = 21235 = 00				
					Rs = 87043 = 00

Continuation

Sch. XLV-Form No. 134

[illegible]

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			13.2	RA=	130500=00
(Item 8) Repair of old joint sealant do-do					
Quant. vide TMB No. 63					
Item No. 8					
932.0 m @ 23.49/m				RA=	21912=00
(Item 9) maintenance of c/d work (H/P culvert)					
Quant. vide TMB No. 63					
Item - 9					
6.0 No @ 1130.67/m				RA=	6784=00
(Item 10) maintenance of c/d work (slab culvert)					
Quant. vide TMB No. 63					
Item No. 10					
1.0 No @ 2329.21/m				RA=	2329=00
(Item 11) Road marking					
Quant. vide TMB No. 63					
Item - 11					
250.0 m ² @ 736.00/m ²				RA=	184294=00
(Item 12) Cement concrete ^{concrete} floor ^{portion}					
Quant. vide TMB No. 63					
Item - 12					
186.4 m ² @ 742.00/m ²				RA=	139427=00
Continuation					RA= 485246=00

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			13.12	RA =	485246=00
(Item 13) maintenance of road					
sign etc do					
Quant. vide TMB PN. 63					
Item - 13					
2.25 km @ 1077.81/km RA =					2425=00
(Item 14) maintenance of 100 m					
and 1/2 m stones					
Quant. vide TMB PN. 63					
Item - 14					
2.25 km @ 622.22/km RA =					1413=00
(Item 15) cutting of branches					
of trees do do					
Quant. vide TMB PN. 63					
Item No - 15					
13.0 NO @ 109.74/NO RA =					1427=00
(Item 16) cutting of shrubs					
from roadway do do					
Quant. vide TMB PN. 64					
Item - 16					
1252.0 NO @ 6.73/NO RA =					8426=00

Continuation

RA = 498937=01

U.S. REV. 10-1-70

Continuation