

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3-11- Yearly Maintenance Bill					
Named Work:- Dharampur Mahakant					
to Hariyarpur, Chandli					
Agency:- Onkar Karmad					
App. No:- 30/SBD/2019-2020					
Date of Completion:- 9/9/20					
Measurement:- 15/11/19					

1) Restoration of Raincuts/ Borns with soil - do do					
6x 30.00 x 1.125 x 0.30 =					60.75 m ³
5x 30.00 x 1.125 x 0.20 =					33.75 m ³
1x 12.00 x 0.90 x 0.15 =					2.97 m ³
					97.47 m ³

2) Making up Borns/ Shoulder - do - do					
6x 30.00 x 1.125 =					202.5 m ²
5x 30.00 x 1.125 =					168.75 m ²
4x 30.00 x 1.125 =					135.00 m ²
1x 30.00 x 1.125 =					33.75 m ²
					540.25 m ²

3) Repair of pot holes filled with 75mm BM - do - do - Bit					
4x 0.90 x 0.075 =					3.04 m ³
4x 0.90 x 0.075 =					2.84 m ³
3x 1.20 x 0.075 =					3.24 m ³
10x 0.60 x 0.60 x 0.075 =					0.97 m ³
2x 0.30 x 0.30 x 0.075 =					0.05 m ³
1x 0.45 x 0.45 x 0.075 =					0.02 m ³

Continuation

9.42 m³

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B/F					PSL-240801=0
(1) maintenance R.C.C.					
current do do					Dir
Qty of B/F (17)					1 Nos
@ 2309.07/m ²					2309=0
					PSL-2413110=0
Reduction in As per					
Agreement					PSL-24311=0
					PSL-21879920
15/12/47					
15/12/47					
15/12/47					

material statement

- (1) Earth — 154.14 m³
 (2) Bitumen Emulsion — 0.205 MT
 (3) Bitumen — 1.265 MT
 (4) Aggregates — 21.623 m³

15/12/47
 15/12/47
 15/12/47

Continuation