


3rd year Maintenance Record Entry.

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Name of Work: Const. of RCC					
Bridge over Bhuthi					
River in Korawan Ghana Bigha Rd.					
2) Agency: Pile Engineers India Pvt. Ltd.					
3) Agreement No. - 01/SBD/19-20.					
4) Date of start - 27.05.19.					
5) Date of Completion - 26.05.2020					

3rd year Maintenance

1) Restoration of Raincuts/ Berms with soil, moorum etc.					= 17.72 m ³
2) Making up of Berms/shoulder					= 101.25 m ²
3) Maint. of WBM road, filling of pot holes, ruts					= 1.58 m ³
4) Patch repair over BT surface with 20 mm MSS Type-B					= 21.09 m ²
5) Repair of RCC railing to bring original shape					= 9.88 m
 26/12/20 A.E.					

Continuation

Abstract of Cost

100

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts					
Qty = 17.72 m ³ @ 359.74/m ³ =					6374.00
② Making up of Berms/shoulder					
Qty = 101.25 m ² @ 53.54/m ² =					5421.00
③ Maint. of WBM road incl. Potholes					
Qty = 1.58 m ³ @ 275.95/m ³ =					437.00
④ Patch repair over BT surface with 20 mm MSS Type-B					
Qty = 21.09 @ 197.98/m ² =					4176.00
⑤ Repair of RCC railing					
Qty = 9.88 m @ 3980.79/m =					39314.00
⑥ Total					55,772.00

James
26/12/23
A.E

Material statement: 19

① E/w Qty = 17.72 m³ @ 48.97 =

② James
26/12/23
A.E

4th year Maintenance

Record Entry

4

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Name of work: Const. of RCC Bridge Over Bhuthi River in Korawan Ahana Bigha Road.					
② Agency: Pile Engineers India Pvt. Ltd.					
③ Agreement No. - 01/SBD/19-20					
④ Date of start: 27.05.19					
⑤ Completion Date: 28.05.2020					
4 th year Maintenance					
① Restoration of raincuts				=	20.25 m ³
② Making up of Berms & Shoulder				=	118.13 m ²
③ Maintenance of WBM road including filling potholes etc				=	2.11 m ³
④ Patch repair over BT surface				=	28.13 m ²
⑤ Maintenance of RCC railing				=	9.88 m
Samaes 27/12/21 A.E.					

4th year Maint.

Abstract of Cost

5

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts					
Qty = $20.25 \text{ m}^3 @ 359.74/\text{m}^3 = 7285.00$					
② Making up of Berms/shoulder					
Qty = $118.13 \text{ m}^2 @ 53.54/\text{m}^2 = 6324.00$					
③ Maint. of WBM road					
Qty = $2.11 \text{ m}^3 @ 275.95/\text{m}^3 = 582.00$					
④ Patch repair over BT surface with 20mm Mss					
Qty = $28.13 \text{ m}^2 @ 197.98/\text{m}^2 = 5568.00$					
⑤ Maint. of Rcc railing					
Qty = $9.88 \text{ m} @ 3980.79/\text{m} = 39314.00$					
Total =					59073.00
⑥ Working up of B.M.T					

James
27/12/24
A.E