

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
SHR year Maintenance Bill					
Name of Work:- Maintenance					
of road from PMGSY Ladhari Ke					
Sinhalan more to Nathu Bigha under					
MMGSY (SC)					
Agency: M/S Singh Construction					
Agreement No.: SBD /2018-19					
Actual Date of Completion					
				05/08/2019	
Date of Entry:-					

① Restoration of raincut
With Soil

$2 \times 4 \times 25.0 \text{m} \times 0.90 \text{m} \times 0.30 \text{m} = 54.00 \text{m}^3$
$2 \times 2 \times 30.0 \text{m} \times 0.90 \text{m} \times 0.30 \text{m} = 54.00 \text{m}^3$
$2 \times 30.0 \text{m} \times 0.850 \text{m} \times 0.30 \text{m} = 15.3 \text{ m}^3$
101.70 m^3

② Making up of Berms
Shoulder

$2 \times 4 \times 27.0 \text{m} \times 1.0 \text{m} = 216.0 \text{m}^2$
$2 \times 4 \times 29.0 \text{m} \times 0.850 \text{m} = 197.20 \text{m}^2$
$2 \times 2 \times 25.0 \text{m} \times 0.850 \text{m} = 80.00 \text{m}^2$
$2 \times 2 \times 18.0 \text{m} \times 0.750 \text{m} = 54.00 \text{m}^2$
$2 \times 11.0 \text{m} \times 0.90 \text{m} = 19.80 \text{m}^2$
567.00m^2

③ Repair of pot holes

Filled with BM

$$18.80 \text{m} \times 2.0 \text{m} \times 0.075 \text{m} = 2.82 \text{ m}^3$$

Sch. XLV—Form No. 134