

5th year maintenance bill

62

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W: maintenance of road from Dakshin					
Dumari pa. Anshit dumari Bazar					
to Dakshin puorpi aur jaf.					
(Under mm 65 Bricks NDB)					
Agency: - m/s Bhagwati con. P.V.T. Ltd.					
Agreement No. - 21/SPD/2018-19					
Actual Date of Comp. - 10/01/2020					
Measurement					

Date of measurement: - 10/01/25

1. Restoration of rain/cut with

soil moorum and gravel or a

mixture of best clearing de. less

of soil and stone as per drawing

02 x 11.0m x 02 x 0.75 x 0.30 = 9.90 m³

03 x 15.0m x 02 x 0.60 x 0.30 = 16.20 m³

04 x 05 x 02 x 0.50 x 0.30 = 6.00 m³

01 x 09 x 02 x 0.80 x 0.30 = 3.78 m³

03 x 05 x 02 x 0.80 x 0.30 = 7.20 m³

03 x 15.0m x 02 x 0.60 x 0.30 = 16.20 m³

04 x 05 x 02 x 0.50 x 0.30 = 6.00 m³

3 x 5 x 02 x 0.80 x 0.30 = 7.20 m³

01 x 09 x 02 x 0.70 x 0.30 = 3.78 m³

02 x 11.0m x 02 x 0.75 x 0.30 = 9.90 m³

06 x 05 x 02 x 0.80 x 0.30 = 14.40 m³

6 x 05 x 02 x 0.70 x 0.30 = 12.60 m³

113.16 m³

Limit to 113.0 m³

2. Making up loss of material

irregular on shoulders to the

Continuation

Continuation