

4th year maintenance

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Chandauli					
2. Name of Agency: madhu Devi					
3. Agreement No. 03/SBD/2019-20					
4. Actual date of completion: 20.02.2021					
work done					
① Restoration of pain cuts					
with 60/1 - 10/11					
1x 20.50x 0.90x 0.30 =					5.535
1x 18.10x 0.82x 0.30 =					4.452
1x 10.50x 0.75x 0.32 =					2.52
2x 20.60x 0.72x 0.28 =					16.64
					8.305

8x 10.60x 0.70x 0.30 =	17.808
6x 20.50x 0.65x 0.32 =	25.584
1x 2.50x 0.60x 0.30 =	0.45
	Qty = 64.654m ³
	Say Qty = 64.64m ³

②/2 maintenance of earthen

shoulder - 10/11

1x 20.60x 0.30 =	18.54
2x 30.0x 0.82 =	49.20
6x 20.50x 0.80 =	98.40
5x 18.90x 0.70 =	66.15
5x 20.60x 0.72 =	74.16
2x 30.0x 0.83 =	49.80
2x 3.0x 0.50 =	3.0
	Qty = 359.25m ²
	Continuation Say Qty = 359.10m ²

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 km stone by way of					90651=
refilling - also					
By = 0.95 km wide					
TMD page (62)					
2.75 = 271 km					699=
					91350=
Ramp					
04.02.2025					
J.E.					

Material statement					
(i) earth					118.505m ³
(ii) bitumens 50 -					332.16Kg
(iii) stone chips -					4.487m ³
Ramp					
04.02.2025					
J.E.					

Continuation