

1st year Maintenance Bill

44

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
I) Name of work—Maintenance of road					
Nalanda 21/2 Antarpat Ekayarsai Brahmapur Resthouse Ekayarsai					
Dak bungalow Ke briche se khichda lataha					
Panadorpat road under Ekayarsai P.M.					
II) Name of Aga—Shivnath Deo Ram					
III) Date of start 9-3-2011					
IV) Date of completion 8-3-2011					
V) Actual date of completion - 4/3/2011					
<u>Details of measurement</u>					
Gens(1) Roadcut & concrete works					
Soil and stones ——————					
2x 15mx 0.8 x 0.3 = 7.2 m ²					
2x 8mx 0.9 x 0.3 = 4.3 m ²					
11.52 m ²					
Gens(2) Mank earth sheets					
2x 25mx 0.8 = 40 m ²					
2x 18m x 0.7 = 25.2 m ²					
65.20 m ²					
Gens(3) Bag patch repair					
2x 1.2 x 0.8 = 1.92 m ²					
2x 1.1 x 0.6 = 1.32 m ²					
2x 1.0 x 1.0 = 2.00 m ²					
5.24 m ²					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item(7) cutty bunt trees					

Q'ty as per remdys	1.00			
$\text{Q.L. } 105 = 39$	$\rightarrow \text{E } 105 = 0$			

Item(8) cutty chus but no				
Q'ty as per remdys	2.00			
$\text{Q.L. } 6 = 47$	$\rightarrow \text{E } 13 = 00$			

Item(9) big water				
Q'ty as per remdys	424 L			
$\text{Q.L. } 15 = 75 \text{ P.W.L.}$	$\rightarrow \text{E } 661 = 00$			
Less 20% - C	4 = 00			
	$\star 13477 = 0$			
	$13473 = 0$			

Ans.

22/10/21

J. E / R.A.S.D

Ekomport

Somes

09/03/22

A.B