

Handy-ein maintenance bill

49

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
I) Name of Work - Maintenance of road					
Nalanda 21st Antargat Ekamparsin					
Porokhandke SHASE Ekamparsin Jalbimph					
Ke picche se kha chak hote hae here piron darbar					
tal under Ekamparsin Bloor					
II) Name of Area - Shri Motiampark					
III) Date of start - 9/3/2013					
IV) Date of finish - 2.3.20					
V) Actual Date of work - 4/3/20					
Defects from previous					
Item (1) Restoration of road cuts with					
soil and masonry					
2x	25m x	0.8 x	0.3 =	12.00 m ³	
2x	5m x	0.6 x	0.3 =	1.8 m ³	
					13.8 m ³
Item (2) Maintenance of earth bank					
2x	30m x	0.7	=	42 m ²	
2x	20m x	0.4	=	16 m ²	
2x	5m x	0.3	=	3 m ²	
2x	25m x	0.3	=	15 m ²	
2x	1.7 x	0.6	=	1.2 m ²	
14x	1.6 x	0.3	=	0.48 m ²	
1x	1m x	1.1	=	1.1	
					78.78 m ²

Continuation

[illegible]