

MMESY, T03 to mandacch (Chapradach
Kumhar Tale)

Schedule XLV-Form No. 134

109. below

Ag No. 448BD/19-20

Ag. Value - 59.12293.2.

Arivoli, Shenghathi DIVISION

Agar SUB-DIVISION

Agency - rmls maa shanti court.

Measurement Book

1154

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - T ₃ to MANSADIH					
Agency - MAASHANLI construction					
Agreement No - 77880/19-20					
Item (1) Restoration of Railway					
Berms with soil					
15x 5.10x 1.10x 0.300					25.24 M ³
10x 4.40x 1.15x 0.300					15.18 M ³
13x 4.90x 1.10x 0.300					21.02 M ³
15x 1.80x 1.10x 0.300					8.91 M ³
5x 1.60x 1.15x 0.300					2.76 M ³
					73.11 M ³
				Lim	72.90 M ³
Item (2) Shoulder					
15x 5.50x 1.10					90.75 M ²
14x 6.10x 1.15					98.21 M ²
12x 4.80x 1.10					63.36 M ²
11x 4.50x 1.15					56.92 M ²
10x 5.80x 1.10					63.80 M ²
10x 2.90x 1.10					31.90 M ²
					404.94 M ²
Item (3) Repair of Pot holes					
filled with JSP w.p.m					
8x 2.10x 1.15					19.32 M ²
10x 2.80x 1.10					30.80 M ²
11x 2.50x 1.40					38.50 M ²
2x 1.90x 0.800					2.28 M ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2X	1.10X	0.90		1.98 m ²
					92.88 m ²
item (4)					
					Patch repair over
					Asphalt surface
	10X	5.60X	1.10		61.60 m ²
	5X	2.50X	1.30		16.25 m ²
	8X	1.80X	1.10		15.84 m ²
					93.69 m ²
					104 - 92.88 m ²
Item (5)					
					Maintenance of G.R. work
					H.P. culvert - 4 Hts
Item (6)					
					Maintenance of Road side
					1.10 m 0.15 m
Item (7)					
					Maintenance of road
					and side slope - 0.24 m
Item (8)					
					Cutting of bushes
					of trees - 2 Hts
Item (9)					
					Cutting of plants
					from road - 8 Hts
Item (10)					
					Trimming of grass and
					weeds
	1X	6X	1.15		6.9 m ²
Item (11)					
					White washing of post
	8X	6.00X	0.40		19.2 m ²
	5X	6.00X	0.60		18.0 m ²
	16X	0.40X	0.60		3.84 m ²
					80.64 m ²

Continuation

A. Kumar
28/01/25
R

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
(1/15.10)	Reformation of Rain culs				
	V.T.M.B.P.No - (77)				
	Item (1)	—			22.90 m ³
	Q	371.35/m ³	—		27071=00
(2/15.20)	Mending up of Bony shoulder				
	V.T.M.B.P.No - (77)				
	Item (2)	—			404.94 m ²
	Q	55.95/m ²	—		22656=00
(3/15.30)	Repair of pot holes				
	Filled with 75 mm B.M.				

	Item (3)	92.88 m ²	
	Q	161.33/m ²	14984=00
(4/15.30)	Patch repair over Bituminous Surface		
	V.T.M.B.P.No -	(77)	
	Item (4)	92.88 m ²	
	Q	161.33/m ²	14984=00
(5/15.30)	Maintenance of G.D		
	wires (H.P. Cables)		
	V.T.M.B.P.No -	(78)	
	Item (5)	4 H ₀	
	Q	1109.07/H ₀	4439=00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6/15-3) Maintenance of Road					
Sight					
V.T. M.B.P.H. - (78)					
Item (6) - 0.15 km					
Rs 1063.51/m					160.00
(7/15-11) Maintenance of Drain					
on stone					
V.T. M.B.P.H. - (78)					
Item (7) - 0.24 km					
Rs 725.28/m					174.00
(8/15-20) Cutting of branches					
of Tree					
V.T. M.B.P.H. - (78)					

	Item (8) - 0.20 km				
	Rs 105.39/m				21.00
(9/15-20) Cutting of stumps					
From road way					
V.T. M.B.P.H. - (78)					
Item (9) - 8 Hrs					
Rs 6.42/Hr					52.00
(10/15-17) Trimming of grass					
and weeds					
V.T. M.B.P.H. - (78)					
Item (10) - 6.9 m ²					
Rs 2.16/m ²					15.00
(11/15-17) White washing of					
Parapet					
V.T. M.B.P.H. - (78)					

Continuation

This image shows a full page of blank graph paper. The grid consists of 10 columns and 20 rows of squares. The lines are thin and black, set against a white background. There are no margins or additional markings on the page.

Scanned with CamScanner