

MMBISY (WB) OF MRD/2017-18

102 Khushalpur to Badhiga
(MMBISY - WB)

Schedule XLV-Form No. 134

Baisi DIVISION

Baisa SUB-DIVISION

Measurement Book

Ham construction

1620

2nd year Maintenance

9

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of Red form					
To 2 Khushelpur to Badliye.					
Agency - Algom Construction.					
Agreement No - 07/HB/D/2019-20					
Dated of Commencement - 27/12/2019					
Actual Date of completion - 07/12/2022					
Record Entry					
⊕ Restoration of concrete/					
bedms with soil, medium					
		4x7.50m	1.40m	0.30m	9.60m ³
		3x8.00m	1.05m	0.30m	7.56m ³
		6x6.00m	0.90m	0.30m	9.72m ³
		3x11.00m	0.75m	0.30m	7.43m ³
		4x7.00m	0.95m	0.30m	7.98m ³
		3x10.50m	0.85m	0.30m	8.03m ³
		3x12.50m	0.75m	0.30m	8.44m ³
		5x8.00m	0.80m	0.30m	9.60m ³
		3x9.50m	0.90m	0.30m	7.70m ³
		4x8.50m	0.85m	0.30m	8.67m ³
		3x11.50m	0.75m	0.30m	7.76m ³
		4x10.00m	0.75m	0.30m	9.00m ³
		3x9.00m	1.10m	0.30m	8.91m ³
		4x6.50m	1.20m	0.30m	9.36m ³
		3x12.00m	0.70m	0.30m	7.56m ³
		4x7.50m	0.95m	0.30m	8.55m ³
		3x10.00m	0.90m	0.30m	8.10m ³
		3x9.50m	0.75m	0.30m	6.41m ³
C/o 149.78m ³					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				61 F	149.78 H ²
	3x	10.50 M	0.70 M	3.00 M	15.99 H ²
	5x	7.50 M	0.70 M	3.00 M	6.73 H ²
			Total	1.00 M	160.50 H ²
(2/2) Making up of dressing					
Shoulder stripping excess					
Soil, from the shoulder					
	3x	22.00 M	0.70 M		46.20 H ²
	2x	24.00 M	0.70 M		45.60 H ²
	3x	19.50 M	0.80 M		46.80 H ²
	3x	21.50 M	0.70 M		45.15 H ²
	2x	29.00 M	0.85 M		49.30 H ²
	3x	23.00 M	0.70 M		48.30 H ²
	3x	18.50 M	0.90 M		49.95 H ²
	2x	26.00 M	0.95 M		46.80 H ²
	3x	17.00 M	0.85 M		43.35 H ²
	5x	11.50 M	0.80 M		46.00 H ²
	3x	16.50 M	0.80 M		39.60 H ²
	4x	15.00 M	0.95 M		57.00 H ²
	3x	21.00 M	0.75 M		47.25 H ²
	3x	20.50 M	0.80 M		49.20 H ²
	2x	28.00 M	0.90 M		50.40 H ²
	3x	17.50 M	0.80 M		42.00 H ²
	2x	27.50 M	0.85 M		46.75 H ²
	2x	23.50 M	0.90 M		42.30 H ²
	3x	19.00 M	0.85 M		48.45 H ²
			Total		890.40 H ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3/4) Patch repair of road potholes with 11" seed surface.					
2x	3.25m	1.35m			8.78m ²
2x	2.90m	1.40m			8.12m ²
3x	1.90m	1.30m			7.41m ²
3x	2.25m	1.45m			9.79m ²
2x	2.50m	1.55m			7.75m ²
3x	1.25m	1.25m			4.69m ²
3x	1.50m	1.45m			6.53m ²
2x	1.75m	1.65m			5.78m ²
3x	2.75m	1.25m			10.31m ²
2x	3.50m	1.30m			9.10m ²
2x	2.75m	1.50m			8.25m ²
3x	2.00m	1.25m			11.25m ²
2x	2.90m	1.35m			7.83m ²
3x	1.75m	1.45m			7.61m ²
4x	2.25m	1.20m			10.80m ²
				Totally	124.00m ²
(4/6) Maintenance of H.P.					
Culvert					2.0 Nos.
(5/7) Maintenance of Lab					
Culvert					7.0 Nos.
(6/8) Maintenance of Road					
Sign					0.31 km
(7/9) Maintenance of road					
and km sign					0.39 km

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9/10) Cutting of branches of trees and shrubs. 5 Nos.					
(7/10) Cutting of shrubs from Rectangular 2 Nos.					
(10/10) Trimming of grass and weeds.					
	1x	3.01m	0.75m		2.25m ²
	1x	3.01m	0.95m		2.85m ²
	1x	3.01m	0.80m		2.40m ²
	1x	3.01m	0.70m		2.10m ²
	1x	3.01m	1.40m		3.00m ²
			Totally		12.60m ²
(11) White coating of parapet walls of CD work.					
	2x2x	6.20m	1.60m		39.68m ²
	2x4x	0.40m	0.80m		1.92m ²
			Totally		41.60m ²
Sd/- 20/12/2019					

2nd year Maintenance

Abstract of cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of Rd from To 2 Khushke/pad to Badliya.					
Agency - Alam Construction.					
Agreement No - 07 MBD/2019-20					
Date of Commencement - 27/12/2019					
Actual Date of Completion - 07/12/2022					
(1) Restoration of road works					
berms with soil, medium.					
160.50 m ³	QIV. T.H.B.P. 951	1/2			
	@ Rs. 380.58/m ³				Rs. 61083.00
(2) Making up of berms/					
shoulder stripping excess					
soil, from the shoulders.					
890.40 m ²	QIV. T.H.B.P. 1051	3/2			
	@ Rs. 58.37/m ²				Rs. 51973.00
(3) Patch repair over potholes					
with Mix Seal surfacing.					
124.00 m ²	QIV. T.H.B.P. 1151	3/4			
	@ Rs. 241.55/m ²				Rs. 29952.00
(4) Maintenance of H.P. Culvert					
2.00 Nos	QIV. T.H.B.P. 1151	1/8			
	@ Rs. 1117.2/each				Rs. 2234.00
(5) Maintenance of S/C Box Culvert					
7.00 Nos	QIV. T.H.B.P. 1151	5/2			
	@ Rs. 2309.04/each				Rs. 16163.00
(6) Maintenance of Road					
sign.					

Total Rs. 1,61,405.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Continuation