

MMGSY Report L036 effect day 1

Schedule XLV Form No. 134. (EN)

MMGSY (EN)

DIVISION

SUB-DIVISION

Ranjan

Priya

Measurement Book

1379

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					$\approx 35.94 \text{ m}^2$
Rain M					
20/07/2024					
J.E					
Absentee of Cont					
① Restoration of Rain culz					
vide TMB /P-51 = 104.52 m^3					
@ Rs 380.67 per m^3					≈ 39788.0
② Maintenance of earthen Shoulder					
vide TMB /P-51 = 340.32 m^2					
@ Rs 58.60 per m^2					≈ 20412.0
③ Maintenance of B.T. Surface Road					
vide TMB /P-52 = 539.02 m^2					
@ Rs 299.38 per m^2					≈ 161372.0
④ Patch Repairn already filled poth					
vide TMB /P-52 = 537.86 m^2					
@ Rs 247.43 per m^2					≈ 133083.0
⑤ Maintenance of Road sign					
vide TMB /P-52 = 1.55 km					
@ Rs 1047.26 per km					≈ 1623.0
⑥ Cutting of branches of tree shrub					
vide TMB /P-52 = 9.0 NO					
@ Rs 102.53 each					≈ 923.0
⑦ Trimming of trees Neds					
vide TMB /P-52 = 1306.0 m^2					
@ Rs 210 per m^2					≈ 2743.0
Continuation					≈ 359944.0

