


Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: 1060 Annu Mishra ke ghau Se					
Shiv Nagar School Tak					
Agency - Ravi Kumar kumar					
D.O.C - 03.07.2024					
Actual D.O.C - 03.06.2023					
App. No - C2 (SBD) / 2024-22					
Details -					
① Restoration of Rain Gutter -					
R.H.S	10 x	3.15 x	0.75 x	0.35 =	8.27
	18 x	3.25 x	0.85 x	0.30 =	14.92
	16 x	2.70 x	0.70 x	0.30 =	9.07
	10 x	3.55 x	0.30 x	0.35 =	09.94
	15 x	3.60 x	0.70 x	0.30 =	11.34
L.H.S	17 x	2.50 x	0.65 x	0.30 =	8.29
	20 x	2.65 x	0.70 x	0.35 =	12.98
	24 x	3.00 x	0.60 x	0.30 =	12.96
					13.23
	20 x	2.70 x	0.70 x	0.35 =	13.26
					101.00 m ²
② Making up of Benches & chaulder -					
	15 x	7.00 x	0.30	—	84.00
	17 x	6.00 x	0.75	—	76.50
	14 x	8.00 x	0.85	—	95.20
	16 x	5.00 x	0.90	—	72.00
	10 x	4.00 x	0.70	—	28.00
					355.70 m ²
③ Patch repair over Bituminous Surface -					
	6 x	2.45 x	1.75	—	25.73
	2 x	1.70 x	1.10	—	3.74
					29.47 m ²

Continuation


Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
0.179 km @ R		1104.58/km	R		198 =
(C) point 4 200 m f km slope					
Qty like this @ (12)					
0.214 km @ R		637.66/km	R		136 =
					Rs. 75377 =
Acid 6st + 6.00 (3st)			4) R		9799 =
Acid 5.00			4) R		561 =
					R. 85797 =
Less Below 11.24%			4) R		9611 =
					R. 76126 =
					
08/06/29					
JE					

Material

Qty = 154.36 m³Spills - 0.796 m³

Return - 0.068 MT


 08/06/29
 JE