

2nd Year Maintenance

6

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road					
from Rampur Naika Tola To					
Rampur Koral (Ministry-NDB)					
Agency - Ravi Construction					
Agreement No - 13500/2019-20					
Date of start - 14/07/2020					
Actual date of completion - 30/06/2022					
2nd year maintenance 20/07/2023 to					
period 30/07/2024					
① Restoration of Pavements					
2 X	8.00	X 1.25	X 0.30 =	6.00H	
3 X	10.00	X 1.20	X 0.30 =	10.80H	
2 X	9.00	X 1.25	X 0.25 =	5.62H	
2	X 10.50	X 1.20	X 0.25 =	6.30H	
4	X 8.50	X 1.25	X 0.30 =	12.75H	
3	X 9.50	X 1.15	X 0.25 =	8.91H	
2	X 10.60	X 1.25	X 0.30 =	7.95H	
2	X 9.00	X 1.25	X 0.30 =	6.75H	
2	X 10.60	X 1.25	X 0.30 =	7.95H	
1	X 8.00	X 1.20	X 0.25 =	2.40H	
1	X 7.50	X 1.28	X 0.30 =	2.88H	
2	X 7.00	X 1.20	X 0.25 =	4.20H	
3	X 9.00	X 1.10	X 0.30 =	8.91H	
2	X 7.80	X 1.20	X 0.25 =	4.68H	
2	X 7.50	X 1.25	X 0.30 =	5.62H	
4	X 10.00	X 1.20	X 0.30 =	14.40H	
2	X 8.30	X 1.10	X 0.25 =	4.56H	

Continuation

119.96H³

Abstract of cast

9

Sch.XLV-Form No. 134

Sch.XLV-Form No. 134					
Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
(1) Restoration of boundary Q-V70B/8(6)=119.96m ² e R 365.25/11 R 43,815=0					
(2) Maintenance of earthen shoulder Q-V70B/8(7)=736.71m ² e R 541.37/11 R 4,0055=0					
(3) Maintenance of bitumen surfaced road Q-V70B/8(8)=25.40m ² e R 292.58/11 R 7432=0					
(4) Maintenance of H.P culvert					
Q-V70B/8(9)=2.11km e R 1131.04/km R -2263=0					
(5) Maintenance of road sign Q-V70B/8(10)=1.712km e R 1087.63/km R 1860=0					
(6) Maintenance of 200m store Q-V70B/8(11)=1.710km e R 749.40/km R 1281=0 R 96,706=0 Less 10% below → 9,671=0 R 87,035=0					
Shoulder & road net					

Continuation

30/7/24
AC

$\frac{15}{2-2.5}$
 $\frac{15}{-0.5}$
 -30

C/2
07/02/25
RE

~~all maps~~