

# 5th year Maintenance Abill

85

Sch. XLV-Form No. 134

| Particulars                            | Details of actual measurement |      |      |      | Contents of area     |
|----------------------------------------|-------------------------------|------|------|------|----------------------|
|                                        | No.                           | L.   | B.   | D.   |                      |
| Name of work- Maintenance of Road from |                               |      |      |      |                      |
| Pindol Pul To Pindol Devi Asthan-      |                               |      |      |      |                      |
| Agency-                                | Brahm Bakash chandhari        |      |      |      |                      |
| App. No-                               | SBD-49/2018-19                |      |      |      |                      |
| Actual date of completion-             | 12/01/2020                    |      |      |      |                      |
| <u>MEASUREMENT</u>                     |                               |      |      |      |                      |
| ① Restoration of rain cuts             |                               |      |      |      |                      |
| .....20.....20.....42                  |                               |      |      |      |                      |
|                                        | 12                            | 3.60 | 1.00 | 0.30 | 12.96m <sup>3</sup>  |
|                                        | 10                            | 3.95 | 0.90 | 0.30 | 10.125m <sup>3</sup> |
|                                        | 18                            | 1.90 | 0.90 | 0.30 | 9.234m <sup>3</sup>  |
|                                        | 14                            | 1.35 | 1.00 | 0.30 | 5.670m <sup>3</sup>  |
|                                        | 8                             | 2.40 | 1.00 | 0.30 | 5.760m <sup>3</sup>  |
|                                        |                               |      |      |      |                      |
|                                        | 6                             | 4.20 | 0.90 | 0.30 | 6.804m <sup>3</sup>  |
|                                        | 4                             | 4.70 | 0.90 | 0.30 | 5.076m <sup>3</sup>  |
|                                        | 2                             | 5.60 | 0.90 | 0.30 | 3.024m <sup>3</sup>  |
|                                        | 1                             | 5.80 | 1.00 | 0.30 | 1.740m <sup>3</sup>  |
|                                        | 1                             | 6.35 | 0.90 | 0.30 | 1.715m <sup>3</sup>  |
|                                        | 1                             | 7.50 | 0.90 | 0.30 | 2.025m <sup>3</sup>  |
|                                        | 1                             | 6.85 | 1.00 | 0.30 | 2.955m <sup>3</sup>  |
|                                        | 1                             | 7.20 | 1.00 | 0.30 | 2.160m <sup>3</sup>  |
|                                        | 1                             | 6.40 | 1.00 | 0.30 | 1.92m <sup>3</sup>   |
|                                        | 2                             | 4.70 | 1.00 | 0.30 | 2.820m <sup>3</sup>  |
|                                        | 1                             | 7.90 | 0.90 | 0.30 | 2.133m <sup>3</sup>  |
|                                        | 4                             | 6.40 | 0.80 | 0.30 | 6.144m <sup>3</sup>  |
|                                        | 2                             | 7.00 | 0.80 | 0.30 | 3.360m <sup>3</sup>  |
|                                        |                               |      |      |      | 85.625m <sup>3</sup> |

Continuation



**Continuation**