

Annual Maintenance

81

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Jagai Mahalpur to Chandapur via Khaspur					
Agency: Shri Mahendra Singh					
Ass No: 68KBD/18-19					
Actual Date of Completion: 7.3.20					
① Restoration of water cuts - Tse.					
	2x9	30.00	0.30	0.45	= 72.90m ³
				Total =	72.90 "
② working up of Berms shown for - Tse.					
	2x9	30.00	0.50		= 270.00m ³
	2x4	30.00	0.30		= 72.00 "
				Total =	342.00 "
③ repair of path holes with 25 mm layer					
	1x	8.50	3.75	0.025	= 2.39m ³
	1x	18.56	2.50	0.025	= 3.48 "
				Total =	5.87 "
④ patch repair over path holes with 20mm concrete layer - Tse.					
	1x	8.50	3.75		= 31.88 "
	1x	18.56	2.50		= 47.57 "
				Total =	79.45 "
⑤ patch repair over bituminous road					
	1x	9.50	2.10		= 19.95m ³
	1x	10.50	3.00		= 31.50 "
	1x	3.60	3.11		= 11.20 "
				Total =	62.65 "

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				8' 6"	927692
(5) Pile repair over bit 54 hole					
welded on No. (5) VTOP (81)					
			253.44/m		158725
(6) Repair of 110 No. 110					
welded on No. (8) VTOP (52)					
			1109.67/each		66582
(7) Repair of 110 No. 110 (5' 6")					
welded on No. (9) VTOP (83)					
			2291.44/each		22912
					117590
			0.04%		67472
					1175432


 14/03/24
 A.E.

Material Statement

- (1) S/m - 54.11/3
- (2) Stone chips - 3.90 + 3.38 = 7.28 m³
- (3) Bitumen - 5.90 631.51 kg


 14/03/24
 A.E.