

5th Year Maintenance

21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work- Maintenance of road from Kurmi Tola to Malah Tola under MMSY					
Agency- Sujit Kumar					
Agreement No- 039BD/2019-20					
Actual date of completion-					
① Restoration of Raincuts					
1 X	7.50	X 1.10	X 0.25	=	2.06 m ³
1 X	8.10	X 1.20	X 0.30	=	2.88 m ³
2 X	6.50	X 1.25	X 0.25	=	4.06 m ³
2 X	11.10	X 1.28	X 0.30	=	8.45 m ³
2 X	8.50	X 1.25	X 0.25	=	5.31 m ³
1 X	9.20	X 1.25	X 0.30	=	3.45 m ³
2 X	10.10	X 1.10	X 0.25	=	5.50 m ³
1 X	7.10	X 1.10	X 0.30	=	2.31 m ³
1 X	6.50	X 0.90	X 0.30	=	1.75 m ³
1 X	5.10	X 0.90	X 0.30	=	1.35 m ³
2 X	8.10	X 1.20	X 0.30	=	5.76 m ³
1 X	7.20	X 1.20	X 0.25	=	2.16 m ³
1 X	6.10	X 0.80	X 0.25	=	1.20 m ³
2 X	4.50	X 0.75	X 0.30	=	2.02 m ³
1 X	7.10	X 0.90	X 0.30	=	1.92 m ³
2 X	8.10	X 1.25	X 0.30	=	6.00 m ³
2 X	11.50	X 1.25	X 0.25	=	7.19 m ³
2 X	9.50	X 1.25	X 0.25	=	5.94 m ³
2 X	10.25	X 1.10	X 0.30	=	6.76 m ³

Continuation

76.07 m³

Sujit Kumar
5/12/2024
J.E

Sujit Kumar
06/12/24
J.E

Scanned by CamScanner