

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, पीरो (भोजपुर)

पत्रांक 193

/पीरो दिनांक 11.02.2025

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल पीरो, भोजपुर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी सह-सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- योजना शीर्ष बिहार ग्रामीण पथ अनुरक्षण नीति-2018 के तहत पथों की अधियाचना के संबंध में ।

महाशय,



उपर्युक्त विषय के संबंध में सूचित करना है कि योजना शीर्ष बिहार ग्रामीण पथ अनुरक्षण नीति-2018 के अंतर्गत प्रमंडल में चल रहे कार्य के मद में भुगतान हेतु संलग्न प्रपत्र में आवंटन की अधियाचना की गई है ।

अतः अनुरोध है कि कुल 4.93134 (चार लाख तिरानबे हजार एक सौ चौंतीस)

मात्र आवंटन उपलब्ध कराने की कृपा किया जाय, जिससे संवेदक का भुगतान किया जा सकें ।

अनु०-यथोक्त ।

विश्वासभाजन


11/02/25
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल पीरो, भोजपुर

11.02.25

Requisition Format for Scheme Head - 5 Year Maintenance of MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Division :- RWD PIRO

Name of Circle :- ARA

Name of Road																		
Sl NO.	Name of Road	Batch No.	Project ID as per MIS	Administrative Sanction Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lacs.)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	IRI As per Bump Report	Current Maintenance Demand (in Lacs)				Total	Remarks
1	2	3	4	5	Length (in KM)	Amount (in Lakh.)	Initial Rectification with Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)					1st Qtr. Maint. Demand	2nd Qtr. Maint. Demand	3rd Qtr. Maint. Demand	4th Qtr. Maint. Demand		
1	PWD Road to Bastivancola	RM/BH/PIR/19/0005	14181031826	2012 & 02.07.2019	1.000	34.422	19.732	7.31637	05/M.B.D./M/R-2019-20 & 27.01.2020	26/10/2020	25/02/2021	3318	0.36582	0.36582	0.36582	0.00000	1.09746	Completed
2	PWD Road - Deochanda	RM/BH/PIR/19/0005	NEA220001536		1.420	43.457	25.003	9.95589		26/10/2020	15/10/2020	3292	0.49779	0.49779	0.49779	0.49779	1.99116	Completed
3	Piro Agaton - Jagdishpur	RM/BH/PIR/19/0004	NEA220001580		1.300	39.526	22.461	9.2137		26/10/2020	12/10/2020	3404	0.46068	0.46068	0.46068	0.46068	1.84272	Completed
Grand Total :-					3.720	117.405	67.196	26.48596						1.32429	1.32429	1.32429	0.95847	4.93134

Prashant Kumar
11/02/21
DIVISIONAL ACCOUNTS OFFICER
R.W.D. Works Division, Piro

21/02/21
Executive Engineer
Rural Works Department
Works Division, Piro

FORM GFR 19-A**(See Government of India's Decision (1) below Rule-150)****Form of utilisation Certification up to month of UPTO 08.02.2025****MR (3054) under Five Year Routine Maintenance Of****Bihar Rural Road Maintenance Policy – 2018****R.W.D. Works Division-Piro (Bhojpur)**

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs. Lacs)	Amount Received (In Rs. Lacs)	Particulars
1.	Construction of Rural Road under MR (3054) under Five Year Routine Maintenance Bihar Rural Road Maintenance Policy – 2018 (Maintenance)	Secretary cum Empowered officer B.R.R.D.A Letter No- Date-	299.77804	Certified that out of Rs 299.77804 Lacs of grant in aid received during the Year 2023-24 in favour of Executive Engineer RWD Bihar R.W.D. Piro A sum of Rs 275.43554 Lacs has been utilized for the purpose of MR (3054) under Five Year Routine Maintenance Bihar Rural Road Maintenance Policy – 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 24.34250 Lacs remaining unutilized at the end of the period under.
		Total	299.77804	

2. Certified that I have satisfied myself that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- VII. Works have been supervised by Executive Engineer/ Superintending Engineer.
- VIII. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- IX. Construction material have been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical progress achieved:

- i. Construction of Road Works.
- ii. Construction of CD Works.

Pradeep Singh
11.02.25
Divisional Accounts Officer
R.W.D. (W) Div, Piro

21/02/25
Executive Engineer
R.W.D. (W) Div, Piro

ROAD NAME - P W D ROAD TO BASAWANTOLA CONTRACTOR NAME - SACHIN KUMAR SINGH

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
27/01/25	16:44:0	22	0.1	310	30.1	3100	3205	G	25.39313	84.383535	Normal
27/01/25	16:44:30	22	0.1	330	31.2	3300	3396	G	25.392642	84.384157	Normal
27/01/25	16:44:50	22	0.1	290	30.3	2900	3014	G	25.391793	84.383855	Normal
27/01/25	16:45:15	22	0.1	350	32.5	3500	3587	G	25.391035	84.384107	Curve
27/01/25	16:45:35	22	0.1	310	30.3	3100	3205	G	25.39075	84.384965	Normal
27/01/25	16:45:55	22	0.1	340	31.2	3400	3491	G	25.390435	84.386027	Normal
27/01/25	16:46:10	22	0.1	300	30.3	3000	3110	G	25.390132	84.386902	Normal
27/01/25	16:46:25	22	0.1	320	32.5	3200	3301	G	25.389857	84.387793	Normal
27/01/25	16:46:38	22	0.1	350	30.3	3500	3587	G	25.389365	84.388585	Curve
27/01/25	16:46:51	22	0.1	310	31.2	3100	3205	G	25.38842	84.388955	Normal
27/01/25	16:47:06	22	0.1	330	30.3	3300	3396	G	25.388277	84.388938	Normal
Total Length :			1.1			Average :		3318			

$$Y = 0 * X^2 + 0.954 * X + 247.7$$


$$X = 3300$$


$$Y = 3356$$


(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001



 Junior Engineer
 Rural Works Department
 Works Section, Piro


 Assistant Engineer
 Rural Works Department
 Works Sub-Division, Piro


 Executive Engineer
 Rural Works Department
 Works Division, Piro

File :D:\Steco Bump\SEC 22.xlsx Section No. :22, Eqn $Y = 0 * X^2 + 0.954 * X + 247.7$

Name of Customer :SACHIN KUMAR SINGH, Name of Work/ Road :PWD ROAD TO BASAWANTOLA, Lab Job



Sachin
23/11/2015

G.K.
23/11/2015

Sachin
23/11/2015

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD, Works Division, Piro

3rd Quarter

1	Name of the Road	PWD Road to Basawanola		
2	Batch No.	RM/BH/PIR/19/0005		
3	Project ID	14181031826		
4	Total Lenth of Road (in KM)	1.00		
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	1.00		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	7.31637		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	0.36582		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non- Compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00
II	SHOULDERS AND EMBANMENTS	0	10%	0.00
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00
V	VEGATION	0.0001	5%	0.00
TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				0.36582

Date of inspection by E/I or his agent
Prepare by Contractor's self Control unit

Name and Designation of person inspecting road

Date

G.K.
29-1-25
(Signature)

Sent
29/1/25
Signature of person inspecting road

Certify by E/I (Signature) Date:
Executive Engineer
Rural Works Department
Works Division, Piro

RWD, Works Division Piro

3rd Quarter

Government Of Bihar

Rural Works Department

OM(

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road Location:- PWD Road to Basawanola

Position :- A.E.

Length of Road :- 1.000 KM

Date:-

Inspector :- A.E. RWD WORKS SUB DIVISION, PIRO

Period- 26.09.2021 to 25.12.2021

Unit OF Required in each Kilometer

No	standard Of Work Item	Work Unit	1	2	3	4	5	6	7	8	9	10	Comments
OM100	Sealed payment												
OM101	Pothole Patching	m ²	NIL	NIL									No pothole found
OM102	Surface Depression and Rut patching	m ³	NIL	NIL									No Surface Depression and Rut patching found
OM103	Crack Sealing	Lm	NIL	NIL									No crack
	Surface Treatment		NIL	NIL									Not required
OM104	(a) Loss of Agreegate (Surface Ravelling)	m ²	NIL	NIL									No Loss of Agreegate (Surface ravelling) found
	(b) Bleeding / Flushing	m ²	NIL	NIL									No bleeding / furnishing found
	(c) Crocodile Cracking	m ²	NIL	NIL									No Crocodile cracking found
OM105	Edge Repair	m ²	NIL	NIL									Notified & repaired
OM106	Digouts	m ²	N.A.	N.A.									
OM107	Concrete pavement	m ³	N.A.	N.A.									
	Other activities												
OM200	Shoulder												
	Unsealed Shoulder												
OM201	(a) Edge Drop-off	Lm	NIL	NIL									No Edge Drop off found
	(b) Roughness, Scouring or Potholes	Lm	NIL	NIL									No Roughness, Scouring or Potholes found
	(c) Holding water	Lm	NIL	NIL									No Holding Water Found
OM202	Embankment Repair	M ³	NIL	NIL									Notified & repaired
	Other activities (Rain Cuts)		N.A.	N.A.									
OM300	Drainage including culverts major												NA
OM301	Surface Drains & Verge	Lm	N.A.	N.A.									DONE
OM302	Culvert Cleaning	No	NIL	NIL									DONE
OM303	Culvert and pit Repair	M ³	NIL	NIL									Not required
	Other activities (Whirl washing)	M ²	NIL	NIL									
OM400	Vegetation												Need More Cleaning
	Grass Control												Done
OM401	(a) Roadside- General Tidy	Ila	NIL	NIL									Done
	(b) Clear near Safety signs, kilometer posts and roadside furniture	Ila	NIL	NIL									Done
	Tree and Shrub Management	No	NIL	NIL									Done
OM402	Cutting Of Branches Of Trees	No	NIL	NIL									Done
	Cutting Of Shrubs From Road Way	No	NIL	NIL									Done
	Other activities (Trimming of Grass)	M ²	NIL	NIL									Not Required
OM500	Safety Signage and Road												Not Required
OM501	Signs Maintenance	No	NIL	NIL									N.A.
OM502	Guard Stones	Lm	NA	NA									N.A.
OM503	Distance Stones	No	NA	NA									Not Required
OM504	Road Marking	M ²	NIL	NIL									
	Other activities												

Sanj
20/12/21
J.E. RWD WORKS
Section, Piro

Sanj
20/12/21
A.E. RWD WORKS
SUB DIVISION, Piro

Sanj
20/12/21
Executive Engineer
Rural works Department
Works Division, Piro