

10/5 Adarshi construction

DHANDHAR TO DHARMUCHAR

Shedule XLV Form No. 134.

MMGSY (GEN)

E. E. R. W. D. (W)

DIVISION
GAYR

A. E. R. W. D. (W)

SUB-DIVISION
WAZIRGANJ

Measurement Book

2812

W

1st Year Maintenance Bill

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Const. of road from					
Agency - M/S. Anand Singh Const.					
Ag. No - 54 / MHSY / 600 / S.B.D. / 19-20					
Draw - 19.09.19					
Top - 18.09.20					
Date of measurement - 20.12.24					
AOC - 15/12/23					
(2) Restoration of original					
cut.					
(2) Making up of road					
shoulder.					
(3) Repair of pot hole					
(4) Patch repair over					
pot hole.					
(5) Patch repair over					
bituminous.					
(6) Filling of cracks					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		Abstract of Cell			
(1)		Restoration of drain			
		C/W.			
P/37		78.724 ³			
		380=58		P ₂ = 29959=00	
(2)		Making up of Broom			
		Shoulder, striping			
		excess set.			
P/37		437.344 ²			
		58=37		P ₂ = 25528=00	
(3)		Repair of Pat holes			
P/37		2.114 ³			
		10057=26		P ₂ = 1107=00	
(4)		Patch repair over			
		potholes.			
P/37		36.454 ²			
		234=11		P ₂ = 10356=00	
(5)		Patch repair over			
		bituminous.			
P/37		36.454 ²			
		288=25		P ₂ = 10507=00	
(6)		Filling of cracks			
P/37		155.5004			
		4=69		P ₂ = 7293=00	
(7)		Repair of isolated			
		area damaged.			
P/38		3.874 ²			
		284=11		P ₂ = 1100=00	

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15)	White walling of parapet.				
P/38		126.00 M ²			
		@ 16 = 21		16 = 2048 = 00	
(16)	Filling of road				
P/38		1555.00 M			
		@ 4 = 69		16 = 7293 = 00	
				16 = 120592 = 00	
	Below 10% (-)				
				16 = 12059 = 00	
				16 = 108583 = 00	
Checked 20/12/24 JE					
Material statement					
(2)	EW - 78.24 M ³				
(22)	S/Chips - 0.984 M ³				
(222)	Bitumen - 0.06 M ³				
Checked 20/12/24 JE					

Continuation