

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year Maintenance Bill					
N/W - Const. of Road from					
PMGHSY Road to Bhalyni					
Kham Village Simam Tak.					
Agency: - Santosh Kumar					
Ag. No: - 327 SBD / 2021-22					
Date of Work Order: - 06.08.2021					
Actual date of Completion: - 30.5.2023					

① Restoration of rain	
Cuts and berms	
5 x 7.80 x .90 x .30 =	10.53m ³
7 x 9.30 x .95 x .30 =	18.55 "
5 x 8.0 x .90 x .30 =	10.80 "
6 x 8.5 x .90 x .30 =	13.77 "
3 x 7.5 x .80 x .30 =	5.40 "
C.O.D. =	

Lt. 54.88m³

2. making up berms	
and shoulder do	
do. (1)	
6 x 7.50 x .90 =	40.50m ³
7 x 9.35 x .90 =	58.90 "

11 x 9.85 x .95 = 102.93 "

10 x 7.5 x .90 = 67.95 "

6 x 8.30 x .90 = 44.82 "

C.O.D. =

Lt. 304.88m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
1	Restoration of rain cuts and berms.				
54.88m ²					
@ 404.06/m ² — Rs					22175.0
2.	making up berms and Shoulder.. do Elg				
304.88m ²					
@ 60.28/m ² — Rs					18378.0
3.	Repair of pot holes with mix seal surface do.. do Elg				
25.41m ²					
@ 270.57/m ² — Rs					6875.0
4/7	Maintenance of H.P Culvert				
03 Nos					
@ 1165.58/Each — Rs					3500.0
5/8	Maintenance of slab Culvert.				
01 Nos					
@ 2394.96/Each — Rs					2395.0
6/10	Maintenance of 200m and Km Post.				
do Elg					
1.87km					
@ 74822/Km — Rs					1399.0
					54722.0

Continuation