

3rd year maintenance

23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - maintenance of					
Road from Rahangawa to 1023					
Agency - Vinay Construction					
Aggr. No. - 11 SRD/2019-2020					
D.O.C - 20.10.2021					
Date of entry -					
① Restoration of Raincuts -					
	2	15	0.75	0.30	$= 7.2 \text{ m}^3$
	2	28	0.85	0.30	$= 14.28 \text{ m}^3$
	2	18	0.80	0.30	$= 8.64 \text{ m}^3$
					30.12 m^3
② making up of Berms/Shoulder -					
	2	18	0.70		$= 25.2 \text{ m}^2$
	2	30	0.70		$= 42 \text{ m}^2$
	2	25	0.70		$= 35 \text{ m}^2$
	2	35	0.70		$= 49 \text{ m}^2$
	2	12	0.70		$= 16.8 \text{ m}^2$
					168.00 m^2
③ Repair of pot holes filled with 75 mm Bm -					
	1.5	0.30	0.45	0.075	$= 0.15$
	6	1.55	0.85	0.075	$= 0.59$
	9	0.75	0.75	0.075	$= 0.37$
	6	2.0	0.93	0.075	$= 0.83$

Continuation

Continuation