

1st year maintenance work.

44

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Sivamasa Kormi Path to Akhchampye, Karim					
Owner - Krishna murari					"
Date - 92/9/2019-20					
Date of start - 09/08/2019					
Date of completion - 08/08/2020					
Actual date of completion - 06/11/2023					
Work done					

(1) Restoration of stairs cuts

$$\begin{aligned}
 & \text{Area} = 2 \times 15 \times 3 \times 3 \times 0.45 = 121.5 \text{ m}^3 \\
 & + 3 \times 2 \times 0.0.45 = 7.5 \text{ m}^3 \\
 & \text{Total Area} = 121.5 + 7.5 = 129 \text{ m}^3 \\
 & \text{Unit Area} = 129 \text{ m}^3
 \end{aligned}$$

(2) Maintenance of boundary shoulder

$$\begin{aligned}
 & 4 \times 4 \times 30 \times 0.40 = 192 \text{ m}^2 \\
 & 7 \times 3 \times 10 \times 0.45 = 94.5 \text{ m}^2 \\
 & 2 \times 4 \times 30 \times 0.40 = 96 \text{ m}^2 \\
 & 3 \times 15 \times 10 \times 0.25 = 112.5 \text{ m}^2 \\
 & \text{Total Area} = 192 + 94.5 + 96 + 112.5 = 505 \text{ m}^2 \\
 & \text{Unit Area} = 505 \text{ m}^2 \\
 & \text{Unit Area} = 486 \text{ m}^2
 \end{aligned}$$

(3) Maintenance of boundary walls

$$\begin{aligned}
 & 10 \times 2.5 \times 0.160 = 40.8 \text{ m}^2 \\
 & \text{Unit Area} = 40.8 \text{ m}^2
 \end{aligned}$$

(4) Maintenance of slab tops

$$\begin{aligned}
 & \text{Area} = 2 \times 10 \times 3 = 60 \text{ m}^2
 \end{aligned}$$

Continuation

Continuation of
at 10/12/26
10/12/26