

2nd years maintenance

87

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: pm 454 m 92 w 97					
to m 42 d 41 t 10 l 9 a n 9 p 42 v 1					
Tola Hole hue manghi Tola					
susta .					
2. Name of Agency: singh construction					
Pvt. Ltd.					
3. Agreement NO. 108 / m B D / 2019-20					
4. Actual dt. of completion: 31.03.2022					
① Restoration of drain cuts					
1 with soil sloper					
$8 \times 20.50 \times 1.0 \times 0.30 = 49.20$					
$7 \times 10.80 \times 0.9 \times 0.30 = 20.412$					
$6 \times 20.60 \times 0.8 \times 0.30 = 29.664$					
$4 \times 18.20 \times 0.80 \times 0.32 = 18.636$					
$6 \times 18.90 \times 0.75 \times 0.30 = 25.515$					
$7 \times 10.80 \times 0.70 \times 0.28 = 14.817$					
$3 \times 15.60 \times 0.82 \times 0.30 = 11.512$					
$8 \times 20.30 \times 0.80 \times 0.30 = 38.976$					
$2 \times 10.50 \times 0.82 \times 0.32 = 5.516$					
Qty = 214.242 m					
Say Qty = 214.14 m					
② maintenance of earthen					
shoulder sloper					
$2 \times 20.40 \times 1.0 = 40.80$					
$4 \times 15.40 \times 0.80 = 55.44$					
$3 \times 20.60 \times 0.85 = 52.53$					

Continuation
2-0. Qty = 148.77 m

P.T.O.

Scanned with CamScanner