

T05-SLSWA To JOYMANGLAP
PUR

Schedule XLV Form No.-134

BIHAR P.W.D.

M.S. K.L.S.

652

MMHSY-HENARAL

DIVISION

RXL

SUB-DIVISION

EC0006239

M/S K.L.S.

MEASUREMENT BOOK 652

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					5th year maintenance
N/w. To S. Siva to Jaimangla byr Agency -					M/S K.L.S
Agg No. 137/19-20					
Date of work order 25/10/19					
Date of completion Actual 20/2/20					
Date of Entry 7/2/25					
(1) Restoration of rain cut with					
soil - do - do - G/L					
	1	20	1.00	.30	6 m ³
	2	22	1.00	.25	11 m ³
	2	28	1.00	.30	16.8 m ³
	2x3+26		1.00	.30	46.8 m ³

2	24	1.00	.30	14.4 m ³
2	22	1.00	.25	11 m ³
				106 m ³

(2) maintenance of Earthen

Shoulder.

2x5x30	1.00	300 m ²
2x5x29	1.00	290 m ²

(3) maintenance of drain 590 m²

10x30	—	300 m
12x25	—	300 m
15 30	—	450 m
10 30	—	300 m

(4) maint of H.P Culvert 1350 m.

(5) maint of Road sign. 700 km.

(6) maint of 2nd mand kanson. 169 km.

(7) Cutting of Branches of tree 4 Nos

(8) Cutting of shrub from Roadway.

Continuation

8 Nos

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9) Trimming of grass and weeds -					
	2 x 8 x 30	1.0	—		480 m ²
	2 x 8 x 30	1.0			480 m ²
(10) White washing of Parohat wall -					960 m ²
	2 x 6 m	1.60			7.2 m ²
	2 x 6 m	1.40			4.8 m ²
	4	1.40	1.60		9.6 m ²
					<u>12.96 m²</u>
material statement					
E/P w -	106 m ³				
	$\frac{106}{1.15}$				
	92.17				

Abstract of cost

- (1) Restoration of raincoat with seal
 106 m³ @ vide T.M. B P 56
 e R 388.11/m³ — R 41140 = w
- (2) maintenance of earthen shoulder
 590 m² @ vide T.M. B P 56
 e R 55.65/m² — R 32833 =
- (3) maint of drain -
 1350 m @ vide T.M. B P 56
 e R 2.67/m — R 3604 = w
- (4) maint of H.P. Culvert
 1 Nos @ vide T.M. B P 56
 e R 1139.12/1 Nos — R 1139 = w

