

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of road - Bishanpur					
Hizam P.A. mangry					
chawle to Bhagwanp					
Sanewali mukhyas					
me primary school					
Gajoo me east					
Sanewali					
Agency - Babbar Kumar					
Ag. no - 95/2 S.D. 20-21					
Actual D.O. Comp. - 28.01.22					
① Restoration of rain cuts/					
Beams					

$$2 \times 2 \times 20.5 \times 1.05 \times 0.30 = 25.83$$

$$10.45 \times 0.90 \times 0.30 = 2.87$$

$$28.70$$

② making up of Beams/
shoulder

$$2 \times 5 \times 30.0 \times 1.15 = 345.0$$

$$\text{Total} = 386.97$$

③ Repair of pot holes with
75 mm x 150 mm

$$2 \times 21.5 \times 0.85 = 36.56$$

$$\text{Total} = 28.48$$

④ Patch repair over bitum
same qty as above - 28.48

Continuation