

300 year maintenance

74

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of road - (Boscul)					
Mathanama road to					
house of Syamalend					
Nandan Roy					
Agency - Vined Kumar					
Ag. no. - MM/BSY/SB/DHS/2020-21					
Act. date of comp - 09/07/21					
D. R. measur -					
① Restoration of gully					
cuts / Beams					
	2	12.50	0.90	0.30	6.75
	1	30.00	0.95	0.30	8.55
	2	30.00	0.90	0.30	16.20
	2	10.20	1.05	0.30	6.43
					37.92
② making up of Beams					
should					
	6	30	1.05	2	189.00
	2	10.85	1.00	2	21.70
					210.70
③ Repair of pot holes					
with 7.5mm 10mm					
	2	13.50	1.40	2	37.80
					Lm - 37.62

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9/15) white wash on parapet wall					
270 m²					
12.48 m ² vide memo (75)					
(a) 16 = 45/m ² - 205 =					
(10/15) Road marking on ST.					
36.0 m ² vide memo (75)					
(a) 721.91/m ² - 69303-					
(11/15) maintenance of already planted trees -					
53 nos. (a) 574 = - 30422 =					
					156937
Add 18-1. GST 11% - 20402 =					

177339-

8/11/25

8/11/25

C/P

A. S. D. K. M.

13/02/25

E.E.