

NIMGSY (ren)

CHERKI LRA ROAD FROM BANDHA MORE TO BELDARI

Ag. No. - 441 MMGSY / S.B.D. 119-20

Schedule XLV-Form No.-134

E. E. P. (c) (w) DIVISION

A. E. P. (c) (w) SUB-DIVISION

GADH GAYA

# MEASUREMENT BOOK

2805

DINESH KUMAR YADAVENDU

Paper id - 67376137

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Ist on A/C Bill
Name of work:					Const of rural road from Charki Dara road from Brinda
					More To Beldari under MMGSY
Agency:					Dinesh Kumar Yadavendu
Act no:	44	MMGSY/SBD			/19-20
Rev:	19-9-19				
T.O.C:	18-9-20				
Date of measurement:	22.5.20				

① Const of ref 2 working

BM individually

1.80 Km

② Cleaning & grubbing

of road side clado

$$10 \times 30.00 \times 7.00 = 2100.00^3$$

~~$$10 \times 30.00 \times 7.00 = 2100.00^3$$~~

$$10 \times 30.00 \times 7.00 = 2100.00^3$$

$$10 \times 30.00 \times 7.00 = 2100.00^3$$

$$0.24 \text{ Hect}$$

③ Const of embankment

Material obtained from

Benton pit clado

all complete job

C/I

4th year Maint Bill

52

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Name of work - Maint of road from</u>					
					Charki Leng road to
					Bandla Hora to Baldasai
					Muktes MM 45Y.
<u>Agency - Dibring kusumya order.</u>					
<u>Ag H No - 44/S AD/HHYSY/19-20</u>					
<u>Date of start - 19/09/19</u>					
<u>ADC - 26/10/20</u>					
<u>Date of Measurement -</u>					
(1)	Restoration of open cuts				
		136.1643			
		100.4448			
(2)	Making up of Banks				
		746.4542			
(3)	Repair of pot holes				
		0.4742			
(4)	Patch repair over Bituminous.				
		157.5941			
(5)	Maint of CDR body				
		5.00 NO			
(6)	Cutting of branches of trees and shrubs				
		10.00 NO			

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
(1) Restoration of road					
cut.					
P/52	136.164 <sup>3</sup>				
	0 380.58	R= 51820=₹			
(2) Making up of Roadsides shoulder.					
P/52	756.45 M <sup>2</sup>				
	0 158.37	R= 44154=₹			
(3) Repair of pot hole(s)					
P/52	0.47 M <sup>2</sup>				
	0 10433=19	R= 4904=₹			
(4) Patch repair over bitumenous.					
P/52	157.59 M <sup>2</sup>				
	0 296.60	R= 46741=₹			
(5) Paint of 10 Ltr/s					
P/52	5.46 M <sup>2</sup>				
	0 117.00	R= 5585=₹			
(6) cutting of branches of trees.					
P/52	10.00 NO				
	0 106.52	R= 1065=₹			
(7) cutting of shrubs from roadway					
P/52	1681.00 NO				
	0 6254	R= 10994=₹			

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8)					
	Trees missing of grass and weeds.				
	P/53	859.0042			
	(1) $a = 13$	$b = 1857 \text{ cm}$			
(9)					
	White working of parapet.				
	P/53	105.0042			
	(2) $a = 21$	$b = 1702 \text{ cm}$			
		$f = 16.88 \text{ cm} = 0$			
	Below 10% (-)	$b = 16.882 \text{ cm} = 0$			
		$f = 1519.40 = 0$			

Chapp  
geophy  
je

### Note(s) / statement

$$(1) L/12 - 136.164^3$$

$$(2) S/1600 - 4.854^3$$

$$(3) P/4000 - 0.2947$$

Chapp  
201124

Continuation