

3rd year Maintenance

88

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road					
from Katraw Pansy to Khairatda					
under MMWSY					
Agency- Amlesh Prasad					
Agreement No- 44 SBD/2019-20					
Date of start- 27/01/2020					
Date of completion - 26/01/2021					
Actual date of Completion - 28/09/2020					
3rd Year Maintenance } 27/09/2022					
Period } to 28/09/2023					
(1) Maintenance of earthen					
- shoulder					
1	X	6.75	X 1.10 =	7.42 m ²	
2	X	6.00	X 1.20 =	7.20 m ²	
3	X	7.00	X 1.25 =	8.75 m ²	
1	X	5.00	X 0.80 =	4.00 m ²	
2	X	9.00	X 1.28 =	11.52 m ²	
3	X	6.00	X 1.20 =	7.20 m ²	
3	X	7.00	X 1.25 =	8.75 m ²	
2	X	7.00	X 1.25 =	8.75 m ²	
2	X	9.00	X 1.20 =	10.80 m ²	
4	X	7.50	X 1.25 =	9.375 m ²	
2	X	9.00	X 1.28 =	11.52 m ²	
4	X	5.50	X 0.85 =	4.675 m ²	
2	X	6.00	X 1.20 =	7.20 m ²	
2	X	8.50	X 1.25 =	10.625 m ²	
1	X	7.10	X 0.90 =	6.39 m ²	
4	X	8.00	X 1.15 =	9.20 m ²	
					318.74 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Restoration of Reircuts					
1	X	10.10	X 0.75	X 0.25 =	1.87H ³
2	X	7.50	X 1.25	X 0.30 =	5.62H ³
2	X	8.50	X 0.85	X 0.25 =	3.61H ³
3	X	7.60	X 1.28	X 0.25 =	6.72H ³
1	V	9.10	X 1.20	X 0.25 =	2.70H ³
2	V	6.10	X 1.25	X 0.25 =	3.75H ³
1	X	4.90	X 0.85	X 0.25 =	1.04H ³
2	X	6.50	X 1.25	X 0.25 =	4.06H ³
1	X	9.20	X 1.25	X 0.30 =	3.45H ³
1	X	7.50	X 1.20	X 0.25 =	2.25H ³
1	X	8.20	X 1.25	X 0.30 =	3.07H ³
3	X	10.10	X 1.25	X 0.30 =	11.25H ³
3	X	7.50	X 1.25	X 0.25 =	7.03H ³
2	X	6.50	X 1.15	X 0.25 =	3.74H ³
1	X	8.50	X 1.28	X 0.30 =	3.26H ³
4	X	7.10	X 1.20	X 0.30 =	10.08H ³
3	X	9.50	X 1.30	X 0.30 =	11.11H ³
2	X	7.50	X 1.20	X 0.30 =	5.40H ³
3	X	8.10	X 1.25	X 0.30 =	9.10H ³
1	X	10.10	X 1.25	X 0.30 =	3.75H ³
1	X	8.10	X 1.15	X 0.30 =	2.79H ³
3	X	8.10	X 1.28	X 0.30 =	9.22H ³
2	X	5.50	X 1.10	X 0.30 =	3.63H ³
2	X	11.10	X 1.28	X 0.30 =	8.45H ³
2	X	7.50	X 1.20	X 0.30 =	5.40H ³
2	X	9.20	X 1.10	X 0.25 =	5.06H ³
2	X	8.00	X 1.10	X 0.25 =	4.10H ³

Continuation

141.31H³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Maintenance of Bituminous surfaced road					
(i) Repair to pot holes					
1	X	2.50	X 1.25 =	3.125 ^L	
1	X	3.00	X 1.50 =	4.50 ^L	
1	X	2.80	X 1.40 =	3.92 ^L	
1	X	2.60	X 1.50 =	3.90 ^L	
1	X	3.10	X 1.30 =	4.03 ^L	
1	X	3.50	X 1.50 =	5.25 ^L	
1	X	3.75	X 1.60 =	6.00 ^L	
1	X	4.10	X 1.60 =	6.56 ^L	
1	X	3.85	X 1.30 =	5.00 ^L	
2	X	4.00	X 1.50 =	12.00 ^L	
4	X	2.00	X 1.25 =	10.00 ^L	
1	X	2.80	X 1.20 =	3.36 ^L	
1	X	4.20	X 1.50 =	6.30 ^L	
2	X	2.50	X 1.50 =	7.50 ^L	
2	X	2.60	X 1.40 =	7.28 ^L	
2	X	2.75	X 1.50 =	8.25 ^L	
1	X	3.00	X 1.60 =	4.80 ^L	
3	X	4.00	X 2.00 =	24.00 ^L	
					125.77 ^L
(ii) Maintenance of WBM road					
Q - same as above =					125.77 ^L
(iii) Patch repairs					
Q - same as above =					125.77 ^L

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Maintenance of earthen shoulder					
2	X	10.00	X 1.25 =	25.00 m ²	
1	X	6.50	X 0.90 =	5.85 m ²	
1	X	8.10	X 1.15 =	9.31 m ²	
2	X	12.00	X 1.20 =	28.80 m ²	
1	X	8.60	X 1.20 =	10.32 m ²	
2	X	10.00	X 1.28 =	25.60 m ²	
3	X	9.00	X 1.25 =	33.75 m ²	
3	X	13.00	X 1.25 =	48.75 m ²	
2	X	10.75	X 1.28 =	27.52 m ²	
2	X	8.10	X 1.15 =	18.63 m ²	
2	X	6.20	X 1.25 =	15.50 m ²	
1	X	7.10	X 0.90 =	6.39 m ²	
3	X	20.00	X 1.20 =	72.00 m ²	
4	X	14.20	X 1.10 =	62.48 m ²	
				389.90 m ²	
(5) (i) Maintenance of slab					
					4 May
(ii) Waste masonry on Parapet.					37.41 m ²
(6) Trimming of grass					
2	X	10 X 30 X 0.50 =		300.00 m ²	
2	X	10 X 30 X 0.45 =		270.00 m ²	
2	X	15 X 30 X 0.48 =		432.00 m ²	
				1002.00 m ²	
(7) (i) cutting of branches of trees - 12 May					
(ii) cutting of shrubs -					24 May

Continuation

Continuation

Abstract of cost

93

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raiments					
Q-VTB P89 ② =	141.31	m ²			
C.R. - 380 =	58/m ²				537800
② Maintenance of earthen shoulder					
Q-VTB P88 ① =	318.74	m ²			
P91 ② =	389.9	m ²			
	708.6	m ²			
C.R. - 58.60/m ² -					4152600
③ Maintenance of bituminous surface road					
(i) Repair to pot hole					
Q-VTB P90 ③ =	125.77	m ²			
C.R. - 349 =	93/m ²				440100
(ii) Maintenance of WBM road					
Q-VTB P90 ③ =	125.77	m ²			
C.R. - 514.78/m ² -					6474400
(iii) Patch repair:-					
Q-VTB P90 ③ =	125.77	m ²			
C.R. - 333.04/m ² -					4188600
④ Maintenance of slab channel					
Q-VTB P91 ⑤ =	4.44	m			
C.R. - 2309 =	03/each				923600
⑤ White washing on parapet walls of CD					
Q-VTB P91 ⑤ =	37.41	m ²			
C.R. - 16.65/m ² -					62300

Continuation 25580600

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ cutting of branches of trees					
Q-VTNB/P 91 (7) = 12 May					
e R - 106.52/each R					1278=00
⑦ cutting of shrubs					
Q-VTNB/P 91 (7) = 24 May					
e R - 6.54/each R					157=00
⑧ Trimming of grass					
Q-VTNB/P 91 (8) = 1002.00 ft					
e R - 2.18/11 ^{ft} R					2184=00
⑨ Painting two coat concrete surface					
Q-VTNB/P 92 (8) = 39.10 ft					
e R - 103.06/11 ^{ft} R					4019=00
⑩ Provision laying Road Marking					
Q-VTNB/P 92 (9) = 399.10 ft					
e R - 851=80/11 ^{ft} R					339,868=00
⑪ Maintenance of road sign					
Q-VTNB/P 92 (10) = 1.995 Km					
e R - 1074.51/km R					2144=00
⑫ Maintenance of 200m Stone					
Q-VTNB/P 92 (10) = 0.359 Km					
e R - 729.07/km R					2621=00
				R	6,05,718=00
Less 0.09% before					545=00
				R	6,05,173=00
Prison 22-11-23 OK					
				R 22/11/23 AE	

Continuation

Continuation