

Figure 6

Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement.

[illegible]

	7X	4.56	X 0.98	X 0.30	= 9.38m ³
	9X	5.83X	1.04	X 0.30	= 16.51m ³
	6X	3.65X	0.96	X 0.30	= 6.31m ³
	12X	6.92X	0.92X	0.30	= 22.92m ³
	5X	4.84X	0.84X	0.30	= 6.10m ³
	8X	7.45X	0.85X	0.30	= 15.20m ³
	11X	6.89X	1.08X	0.30	= 24.56m ³
	9X	7.62X	1.03X	0.30	= 21.19m ³
	8X	6.72X	0.96X	0.30	= 15.94m ³
	13X	6.46X	0.93X	0.30	= 23.43m ³
					161.54m ³
2.	Maint. of earthen				
	Shoulders do —				
	2X9	X 6.42	X 1.34	=	154.85m ³
	2X6	X 4.0	28X 1.41	=	72.42m ³

Continuation $C_0 = 227.27\%$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2x8	X 5.72	X 1.54	=	140.94m ²
	2x	4x 7.26	X 1.38	=	80.15m ²
	2x	5x 6.65	X 1.45	=	96.43m ²
	2x	6x 8.47	X 1.53	=	155.51m ²
	2x	7x 4.77	X 1.64	=	109.52m ²
					809.82m ²
3.	Repair to potholes				
	by removal -do-				
	9	X 3.56	X 1.24	=	39.73m ²
	6	X 4.68	X 1.16	=	32.57m ²
	8	X 5.81	X 1.07	=	49.73m ²
	11	X 3.16	X 1.34	=	46.58m ²
					168.61m ²
4.	Maint. of WBM road				
	road -do-				
	9x	3.56	X 1.24	=	39.73m ²
	6x	4.68	X 1.16	=	32.57m ²
	8x	5.81	X 1.07	=	49.73m ²
	11x	3.16	X 1.34	=	46.58m ²
					168.61m ²
5.	Patch repair on already filled potholes -do-				
	9x	3.56	X 1.24	=	39.73m ²
	6x	4.68	X 1.16	=	32.57m ²
	8x	5.81	X 1.07	=	49.73m ²
	11x	3.16	X 1.34	=	46.58m ²
					168.61m ²
6.	Maint. of slab				
	curb -do- =				LIND.
7.	Maint. of road signs -do- =				3.00km

Continuation

Continuation