

2nd year maintenance

39

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint of Road from Baghi Pabli to Montee Sadole Konth Road to Jagan Rajput dwee tak via Randoni Rai Daxian Balthha and nearby dola					
Agency - Pushpak Project Pvt. Ltd. Bhagwanpur Muzaffarpur					
Agreement No. 17/SBP/2019-20					
Date of Start 18.08.19					
Date of actual comp 29.09.20					

Work Done

C1 Restoration of Rain cut					
do do all comp job					
2x11x	1.1x	0.3	=	7.26	
5x15x	0.7x	0.3	=	15.75	
3x19x	1x	0.3	=	17.10	
2x18x	1.1x	0.3	=	11.88	
2x16x	0.8x	0.3	=	7.68	
2x17x	1x	0.3	=	10.20	
				69.87m ²	

(2) Maint of earthen shoulder do do all comp job					
2x15x	1.1		=	33.0	

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty vide Tms P 40 = 53.41 m ²					
@ R 241.14/m ²					R 12879 = a
(4) Maint. of Hume pipe culvert					
do do all comp jobs					
Qty vide Tms P 40 = 670.					
@ R 1117 = cost each					R 67022 = a
(5) Maint. of Slob culvert					
do do all comp jobs					
Qty vide Tms P 41 = 2 m.					
@ R 2309.03/each					R 4618 = a
(6) Maint. of Road Sign do					
do all comp jobs					
Qty vide Tms P 41 = 1.36 km					
@ R 1074.51/km					R 14612 = a
(7) Maint. of 20m and 10m					
stone do do all comp jobs					
Qty vide Tms P 41 = 1.36 km					
@ R 735.27/km					R 10002 = a
					R 76082 = a
less 10% as agreement					R 7608 = a
					R 68474 = a