

Abstract of work.

44

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- 2nd year maint of road from Gagan G.N. Boudh to Parnari Rai'sola.					
Name of Agency:- M/s. Annapurna Indus. Solution Pvt Ltd.					
Agreement No:- 18 SBD/2019-20.					
Date of commencement of work:- 28/11/19					
Date of completion :- 27/8/2020.					
Act date of completion:- 28/8/2021					
① Restoration of main cut/ditch with soil-mooring etc.					
Qty vide Tm. B.P. 42 -					55.143 m ³
@ Rs. 59/m ³					- Rs 20931 =
② Making up of Berms/Shoulder Striping exc. of soil from the shoulder					
Area vide Tm. B.P. 43 -					240.08 m ²
@ Rs. 56 = 81/m ²					- Rs 13634 =
③ Patch repair over bituminous surface with 20 mm premix surface material					
Area vide Tm. B.P. 43 -					32.30 m ²
@ Rs. 184 = 42/m ²					- Rs 5956 =
④ Maint of C/D works H.P. culverts					
Nos vide Tm. B.P. 43 -					300 Nos
@ Rs. 1102 = 80/Nos					- Rs 3308 =

Continuation

Continuation

Abstract of cost.

50

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-	3rd Year maintenance of road from Gogri G.N. Boudh to Ramani Rai tola.				
Name of Agency:-	M/o Anna Purna Infra. solution Pvt. Ltd.				
Agreement No:-	18 SPD/2019-20				
Date of start of work:-	28/11/19				
Date of completion:-	27/8/20.				
Act date of completion:-	28/6/21				

①. Restoration of drains/dens

with self-cleaning, etc.

Qty vide T.M. B-47	-	63.78 m ³	
@ Rs 379 = 59/m ³			Rs 24210 =

②. Making up of Berms/shoulders

stripping excess soil from the shoulder surface,

Area vide T.M. B-48	-	243.00 m ²	
@ Rs 56 = 81/m ²			Rs 13804 =

③. Repair of pot holes filled with

75 mm W.B.M.

Qty vide T.M. B-48	-	48.96 m ³	
@ Rs 306 = 73/m ³			Rs 15019 =

④. Patch repair over pot holes

with 20 mm premix surfacing material

Area vide T.M. B-48	-	50.25 m ²	
@ Rs 166 = 64/m ²			Rs 8373 =

Continuation

Continuation