

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of road from Makhargawan Bypass road to Dubna/179					
Agency - Sri Ram Kariya KUNOR					
Agreement no - 95300/2019-20					
Date of start - 18.12.2019					
Actual completion - 19.03.2022					
Record Entry					
1) Restoration of road with 1.5' soil					
— do —					
4 x 6.50 x 0.80 x 0.30					6.34
6 x 4.90 x 0.90 x 0.30					7.94
8 x 5.80 x 0.85 x 0.30					11.83
9 x 5.60 x 0.95 x 0.30					14.36
6 x 4.70 x 0.90 x 0.30					7.61
9 x 5.40 x 1.05 x 0.30					15.31
7 x 4.75 x 0.75 x 0.30					7.48
Total					70.87
2) Maint of eotery x shoulders do					
2 x 9 x 4.70 x 0.90					76.14
2 x 8 x 5.90 x 1.10					94.40
2 x 6 x 8.60 x 1.10					119.52
2 x 7 x 2.95 x 0.60					24.28
Total					308.84

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2/25 curvy of branches of trees - do.					
06 no. note page (62)					
ch 106.52/area				h	852
3/18 Pruning of grass A needs - do.					
554.00 m ² note page (62)					
ch 2.18/m ²				h	1203
				Rs.	60880
less 0.05/ below				Rs.	30
				h,	60850
<u>Ashta</u> 15/03/23 J.G.					

Materials used		
20024 stone -		70.52 m ²
B. 1/20 stone 1-90 -		44 102
20001 B. 03 R-1		6 102
S. chips -		0.56 m ²
crushed gravel -		0.124 m ²
<u>Ashta</u> 15/03/23 J.G.		