

5th year maintenance

Sch. XLV-Form No. 134

51

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint. of road from					
Jhakara Bazar to Hospital					
Gramhariya ward No. 16 via					
purabi Tola.					
Agency - M/S Raj Construction.					
Agg. No - 53500/MMC/SY/2019-20.					
Date of Start -			18/10/2019.		
Actual completion -			12/01/2021.		

Record Entry

- Restoration of

shoulders - do -

$$7 \times 3.66 \times 1.15 \times 0.30 = 8.84 \text{ m}^3$$

1 X	5.15 X	1.10 X	0.30 =	6.20 m
6 X	4.06 X	1.20 X	0.30 =	8.77 m ³
12 X	6.45 X	1.15 X	0.30 =	26.70 m ³
8 X	7.03 X	1.05 X	0.30 =	17.72 m
6 X	4.15 X	1.10 X	0.30 =	8.22 m
5 X	3.49 X	1.12 X	0.30 =	5.86 m
9 X	5.75 X	1.15 X	0.30 =	17.85 m
7 X	4.24 X	1.18 X	0.30 =	10.51 m
4 X	7.45 X	1.20 X	0.30 =	10.73 m
				122.001

- Maint. of Gutter

shoulder - do -

2 X 7	X 9.95	X 0.95 =	124.36 m ³
2 X 12	X 6.40	X 1.50 =	230.40 m
2 X 8	X 7.44	X 1.60 =	190.46 m

545.22 m³

Continuation

6
ing
low
ckn